LR1.1 WATERCOURSE





LR1.2 CHANNELIZED WATERCOURSE









LR1.3 RESERVOIR



LR1.4 POND

LR2.2 VEGETATED MAN-MADE SLOPE






LR4.1 SHRUBBY GRASSLAND ON HILLSIDE

LR3.2 WOODLAND ON LOWLAND

LR3.1 WOODLAND ON HILLSIDE



LR4.2 SHRUBBY GRASSLAND ON LOWLAND



LR5.1 ACTIVE FARMLAND





LR5.2 INACTIVE FARMLAND





LR5.3 NURSERY



LR6.1 RURAL BUILT/OPEN STORAGE AREA



LR6.2 VILLAGE AREA





LR6.3 TRADITIONAL VILLAGE AREA





LR6.4 INDUSTRIAL/FACTORY AREA




LR6.5 ONGOING DEVELOPMENT



LR6.6 DEVELOPED
TRANSPORT ROUTE







LR6.9 TEMPLE



LR6.10 ROADSIDE PLANTING





Drawn Description Ch'k'd App'd

* Restricted area. Inaccessible to public.

Photorecord not available (LR2.1). Aerial photograph provided from Google Earth.



20/F Two Landmark East 100 How Ming Street Kwun Tong, Kowloon Hong Kong T +852 2828 5757 F +852 2827 1823 W www.mottmac.com.hk



CIVIL ENGINEERING AND DEVELOPMENT DEPARTMENT

AGREEMENT NO. CE45/2008(CE) LIANTANG/HEUNG YUEN WAI BOUNDARY CONTROL POINT AND ASSOCIATED WORKS -- INVESTIGATION

PHOTORECORD OF EXISTING LANDSCAPE **RESOURCES - SECTION C**

Design			Eng.Chk.		
Drawn			Coordination		
Dwg. Chk.			Approved		
Scale at A3		Project		Status	
		CAD file			
Drawing No					Rev
FIGURE 11.5.19					