

Annex G2

Tree Survey Schedule for Sha Lo Tung Road

A Tree No.	B		C Northing (m)	D Easting (m)	E Trunk Diameter (m)	F Trunk Circumference (m)	G Height (m)	H Crown Spread (m)	I			J			K			L			M			N			O Brief comments and description
	Species Name								Common Name	Tree Form	Health Condition			Amenity Value			Survival Rate after Transplantation			Conflict with Development			Proposed Treatment				
	G	F									P	G	F	P	H	M	L	H	M	L	Paritally - Soil Nailing	Yes - New Road Alignment/ Cut Slope	No	Fell	Retain	Transplant	
A0106	<i>Acacia confusa</i>	Taiwan Acacia	835600	836778	0.3	0.94	15	5		1	1			1		1			1		1					Tree has grown on slope. Multiple elongated trunks recorded.	
A0448	<i>Acacia confusa</i>	Taiwan Acacia	835695	836838	0.2	0.63	14	7		1	1			1		1			1		1					Elongated trunk recorded.	
A0452	<i>Acacia confusa</i>	Taiwan Acacia	835696	836841	0.4	1.26	15	8		1	1			1		1			1		1					Broken branches recorded.	
A0455	<i>Acacia confusa</i>	Taiwan Acacia	835699	836845	0.3	0.94	14	5		1	1			1		1			1		1					Tree has grown on slope. Elongated trunk recorded.	
A0478	<i>Acacia confusa</i>	Taiwan Acacia	835703	836847	0.3	0.94	12	8		1	1			1		1			1		1					Tree has grown on slope. Elongated trunk recorded.	
A0506	<i>Acacia confusa</i>	Taiwan Acacia	835720	836853	0.2	0.63	11	3		1	1			1		1			1		1					Tree has grown on slope. Elongated trunk recorded.	
A0790	<i>Acacia confusa</i>	Taiwan Acacia	835863	836911	0.3	0.94	10	8		1	1			1		1			1		1					Tree has grown on slope. Tree growth has been obstructed by other plants. Leaning trunk recorded.	
A0792	<i>Acacia confusa</i>	Taiwan Acacia	835865	836912	0.17	0.53	8	4		1	1	1		1		1			1		1					Tree has grown on slope. Multiple broken trunks recorded.	
A0797	<i>Acacia confusa</i>	Taiwan Acacia	835870	836917	0.35	1.10	14	9		1	1			1		1			1		1					Tree has grown on slope. Multiple trunks recorded.	
A0976	<i>Acacia confusa</i>	Taiwan Acacia	836019	836929	0.15	0.47	6	4		1	1			1		1			1		1					Tree has grown on slope. Multiple leaning trunks recorded.	
A0977	<i>Acacia confusa</i>	Taiwan Acacia	836025	836930	0.15	0.47	8	4		1	1			1		1			1		1					Tree has grown on slope. Multiple leaning trunks recorded.	
A0984	<i>Acacia confusa</i>	Taiwan Acacia	836047	836948	0.25	0.79	8	5		1	1			1		1			1		1					Leaning trunk and broken branches recorded.	
A0986	<i>Acacia confusa</i>	Taiwan Acacia	836050	836953	0.45	1.41	12	8		1	1			1		1			1		1					Multiple trunks recorded.	
A0987	<i>Acacia confusa</i>	Taiwan Acacia	836049	836956	0.22	0.69	11	4		1	1			1		1			1		1					Tree has grown on slope. Elongated leaning trunk recorded.	
A1077	<i>Acacia confusa</i>	Taiwan Acacia	836108	837038	0.25	0.79	12	8		1	1			1		1			1		1					Tree has grown on concrete slope. Multiple trunks recorded.	
A1084	<i>Acacia confusa</i>	Taiwan Acacia	836099	837036	0.35	1.10	16	11		1	1			1		1			1		1					Tree has been twisted by climbers. Multiple trunks recorded.	
A1085	<i>Acacia confusa</i>	Taiwan Acacia	836098	837037	0.35	1.10	13	9		1	1			1		1			1		1					Multiple trunks recorded.	
A1087	<i>Acacia confusa</i>	Taiwan Acacia	836095	837034	0.4	1.26	13	9		1	1			1		1			1		1					Tree has been twisted by climbers. Leaning trunk recorded.	
A1233	<i>Acacia confusa</i>	Taiwan Acacia	836345	837049	0.15	0.47	7	4		1	1			1		1			1		1					Tree growth has been obstructed by other plants in the vicinity.	
A1234	<i>Acacia confusa</i>	Taiwan Acacia	836345	837048	0.15	0.47	6	4		1	1			1		1			1		1					Tree has grown on slope. Leaning trunk recorded.	
A1293	<i>Acacia confusa</i>	Taiwan Acacia	836375	837060	0.25	0.79	12	8		1	1			1		1			1		1					Multiple trunks and dead branches recorded.	
A1295	<i>Acacia confusa</i>	Taiwan Acacia	836382	837062	0.25	0.79	11	6		1	1			1		1			1		1					Tree has grown on slope. Multiple trunks recorded.	
A1361	<i>Acacia confusa</i>	Taiwan Acacia	836409	837045	0.35	1.10	12	10		1	1			1		1		1		1		1				Tree has grown on slope. Leaning trunk recorded.	
A0505	<i>Acacia mangium</i>	Big-leaved Acacia	835717	836850	0.3	0.94	13	6		1	1			1		1			1		1					Tree have been found nearly dead. Broken branches recorded.	
A2043	<i>Acronychia pedunculata</i>	Acronychia	836192	837042	0.13	0.41	8	4		1	1			1		1			1		1					Two main trunks have been recorded. Tree has been recorded on concrete slope and twisted by climbers.	
A2044	<i>Acronychia pedunculata</i>	Acronychia	836195	837044	0.17	0.53	6	5		1	1			1		1			1		1					Two main trunks have been recorded. Tree has been recorded on concrete slope and twisted by climbers.	
A2042	<i>Acronychia pedunculata</i>	Acronychia	836193	837040	0.14	0.44	9	5		1	1			1		1			1		1		1			Two main trunks have been recorded. Tree has been recorded on concrete slope and twisted by climbers.	
A2046	<i>pedunculata</i>	Acronychia	836198	837043	0.17	0.53	7	5		1	1			1		1			1		1					Tree has been twisted by climbers. Elongated trunk has been recorded.	
A2047	<i>pedunculata</i>	Acronychia	836199	837043	0.13	0.41	8	6		1	1			1		1			1		1					Tree has been twisted by climbers. Elongated trunk has been recorded.	
A1563	<i>pedunculata</i>	Acronychia	836584	837015	0.15	0.47	8	6		1	1			1		1			1		1					Leaning trunk recorded.	
A1436	<i>pedunculata</i>	Acronychia	836456	837022	0.17	0.53	5	5		1	1			1		1		1		1		1				Tree has multiple leaning trunks and grows on slope.	
A0032	<i>Alangium chinense</i>	Chinese Alangium	835566	836739	0.25	0.79	8	4		1	1			1		1			1		1					Tree has grown on slope and twisted by climbers.	
A0060	<i>Alangium chinense</i>	Chinese Alangium	835591	836751	0.3	0.94	7	6		1	1			1		1			1		1					Multiple trunks and broken branches recorded.	
A0479	<i>Alangium chinense</i>	Chinese Alangium	835705	836849	0.13	0.41	5	2		1	1			1		1			1		1					Tree has been twisted by climbers and grown on slope. Elongated trunk recorded.	
A0729	<i>Alangium chinense</i>	Chinese Alangium	835813	836906	0.15	0.47	7	2		1	1			1		1			1		1					Tree has grown on slope. Elongated trunk recorded.	
A1062A	<i>Alangium chinense</i>	Chinese Alangium	836084	837022	0.17	0.53	6	5		1	1			1		1			1		1					Tree has grown on slope and twisted by climbers. Multiple trunks recorded.	
A0359	<i>Alangium chinense</i>	Chinese Alangium	835680	836814	0.2	0.63	8	4		1	1			1		1			1		1					Tree has grown on slope. Leaning trunk recorded.	
A0672	<i>Alangium chinense</i>	Chinese Alangium	835806	836894	0.13	0.41	6	1		1	1			1		1			1		1					Tree has grown on slope. Leaning trunk and broken branches recorded.	
A0773	<i>Alangium chinense</i>	Chinese Alangium	835833	836887	0.15	0.47	5	2		1	1			1		1			1		1					Tree has grown on slope and twisted by climbers. Leaning trunk recorded.	
A0123	<i>Aporusa dioica</i>	Aporusa	835621	836802	0.15	0.47	5	3		1	1			1		1			1		1					Tree has been twisted by climbers and grown on slope.	
A0124	<i>Aporusa dioica</i>	Aporusa	835621	836801	0.15	0.47	6	3		1	1			1		1			1		1					Tree has been twisted by climbers and grown on slope.	
A1098	<i>Aporusa dioica</i>	Aporusa	836159	837038	0.1	0.31	5	4		1	1			1		1			1		1					Tree has been recorded on concrete slope. Tree growth has been obstructed by plants in the vicinity. Leaning trunk and imbalanced root recorded.	
A1548	<i>Aporusa dioica</i>	Aporusa	836574	837017	0.12	0.38	5	2		1	1			1		1			1		1					Tree has been twisted by climbers.	
A1683	<i>Aporusa dioica</i>	Aporusa	836671	836953	0.1	0.31	5	1.5		1	1			1		1			1		1					Tree has grown on slope.	
A1761	<i>Aporusa dioica</i>	Aporusa	836736	836893	0.1	0.31	4	1.5		1	1			1		1			1		1					Tree has grown on slope. Broken branches recorded.	
A0727	<i>Aquilaria sinensis</i>	Incense Tree	835822	836902	0.15	0.47	8	5		1	1			1		1			1		1		1			Tree has grown on slope.	
A1267	<i>Aquilaria sinensis</i>	Incense Tree	836331	837038	0.25	0.79	14	8		1	1			1		1			1		1					Tree has grown on slope and twisted by climbers. Multiple trunks recorded.	
A1313	<i>Aquilaria sinensis</i>	Incense Tree	836390	837051	0.3	0.94	16	8		1	1			1		1			1		1					Tree has grown on slope. Elongated trunk recorded.	

Tree No.	Species Name Common Name		Northing (m)	Easting (m)	Trunk Diameter (m)	Trunk Circumference (m)	Height (m)	Crown Spread (m)	Tree Form			Health Condition			Amenity Value			Survival Rate after Transplantation			Conflict with Development			Proposed Treatment			Brief comments and description
									G	F	P	G	F	P	H	M	L	H	M	L	H	Yes - New Road Alignment/ Cut Slope	No	Fell	Retain	Transplant	
A1471	<i>Aquilaria sinensis</i>	Incense Tree	836480	837004	0.13	0.41	6	3																		Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.	
A1494	<i>Aquilaria sinensis</i>	Incense Tree	836548	837007	0.17	0.53	7	3	1	1																Broken branches recorded.	
A1562	<i>Aquilaria sinensis</i>	Incense Tree	836578	837016	0.2	0.63	10	6		1																Multiple elongated trunk recorded.	
A1583	<i>Aquilaria sinensis</i>	Incense Tree	836601	837009	0.3	0.94	13	6		1																Tree has been twisted by climbers and found nearly dead.	
A1606	<i>Aquilaria sinensis</i>	Incense Tree	836628	836996	0.15	0.47	5	3	1	1																Tree has grown on slope.	
A1620	<i>Aquilaria sinensis</i>	Incense Tree	836645	836969	0.15	0.47	6	2		1																Tree has grown on slope. Elongated trunk recorded.	
A1643	<i>Aquilaria sinensis</i>	Incense Tree	836626	836985	0.22	0.69	7	3		1																Tree has been twisted by climbers and found nearly dead.	
A1665	<i>Aquilaria sinensis</i>	Incense Tree	836658	836963	0.1	0.31	6	1.5		1																Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Leaning trunk recorded.	
A1675	<i>Aquilaria sinensis</i>	Incense Tree	836671	836951	0.1	0.31	6	3		1																Tree has grown on slope. Elongated trunk recorded.	
A1677	<i>Aquilaria sinensis</i>	Incense Tree	836674	836952	0.1	0.31	6	2		1																Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Leaning trunk recorded.	
A1680	<i>Aquilaria sinensis</i>	Incense Tree	836673	836952	0.13	0.41	6	3		1																Tree has grown on slope. Multiple elongated trunks recorded.	
A1684	<i>Aquilaria sinensis</i>	Incense Tree	836670	836952	0.1	0.31	5	1.5		1																Tree has grown on slope.	
A1706	<i>Aquilaria sinensis</i>	Incense Tree	836710	836955	0.17	0.53	6	2		1																Tree has grown on slope. Deformed trunk recorded.	
A1720	<i>Aquilaria sinensis</i>	Incense Tree	836714	836913	0.2	0.63	6	6		1																Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.	
A1722	<i>Aquilaria sinensis</i>	Incense Tree	836722	836911	0.2	0.63	5	3		1																Tree has grown on slope and twisted by climbers. Deformed trunk recorded.	
A1723	<i>Aquilaria sinensis</i>	Incense Tree	836719	836910	0.2	0.63	7	4		1																Tree has grown on slope and twisted by climbers. Broken trunk recorded.	
A1730	<i>Aquilaria sinensis</i>	Incense Tree	836724	836906	0.1	0.31	5	2		1																Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.	
A1689	<i>Archidendron clypearia</i>	Monkey-pod	836671	836955	0.15	0.47	5	4		1																Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.	
A1491	<i>Artocarpus styracifolius</i>	Two-coloured Artocarpus , Bicolor Artocarpus	836545	837004	0.22	0.69	13	6		1																	Tree has grown on slope.
A2021	<i>Artocarpus styracifolius</i>	Two-colored Artocarpus	836159	837031	0.15	0.47	10	5		1																Two main trunks have been recorded. Tree has been recorded on concrete slope.	
A0018	<i>Bridelia tomentosa</i>	Pop Gun Seed	835560	836664	0.3	0.94	7	4		1																Tree growth has been obstructed by other plants in the vicinity. Damaged leaning trunk recorded.	
A0021	<i>Bridelia tomentosa</i>	Pop Gun Seed	835557	836674	0.2	0.63	1.5	0.4		1																Tree has been deheaded.	
A0853	<i>Bridelia tomentosa</i>	Pop Gun Seed	835883	836926	0.21	0.66	7	5		1																Elongated trunk and broken branches recorded.	
A0782	<i>Canthium dicoccum</i>	Butulang Canthium	835854	836907	0.25	0.79	10	3		1																Tree has grown on slope and twisted by climbers. Elongated trunk recorded.	
A0828	<i>Canthium dicoccum</i>	Butulang Canthium	835906	836929	0.17	0.53	7	2		1																Tree has grown on slope. Elongated trunk recorded.	
A0926	<i>Canthium dicoccum</i>	Butulang Canthium	836007	836923	0.25	0.79	5	3		1																Tree has grown on slope. Elongated leaning trunk recorded.	
A1242	<i>Canthium dicoccum</i>	Butulang Canthium	836318	837046	0.17	0.53	7	4		1																Tree has grows on slope.	
A1431	<i>Canthium dicoccum</i>	Butulang Canthium	836449	837031	0.3	0.94	11	6		1																Tree has grown on slope. Dead branches recorded.	
A0037	<i>Cassia fistula</i>	Golden-shower	835580	836749	0.15	0.47	6	3		1																Tree has grown on slope and twisted by climbers. Leaning trunk recorded.	
A1382	<i>Cassia fistula</i>	Golden-shower	836439	837040	0.22	0.69	10	6		1																Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.	
A1079	<i>Casuarina equisetifolia</i>	Horsetail Tree	836108	837040	0.4	1.26	15	7		1																Tree has grown on concrete slope. Broken branches recorded.	
A0017	<i>Celtis sinensis</i>	Chinese Hackberry	835560	836661	0.1	0.31	4	2		1																Tree growth has been obstructed by other plants in the vicinity. Damaged trunk recorded.	
A0019	<i>Celtis sinensis</i>	Chinese Hackberry	835559	836666	0.3	0.94	8	4		1																Tree growth has been obstructed by other plants in the vicinity. Broken branches recorded.	
A0029	<i>Celtis sinensis</i>	Chinese Hackberry	835553	836726	0.5	1.57	13	12		1																Tree has been mature in size and grown on slope. Leaning trunk recorded.	
A0034	<i>Celtis sinensis</i>	Chinese Hackberry	835570	836741	0.4	1.26	7	4		1																Tree has grown on slope and twisted by climbers. Leaning trunk recorded.	
A0860	<i>Celtis sinensis</i>	Chinese Hackberry	835960	836921	0.4	1.26	10	5		1																Tree has grown on slope. Broken branches recorded.	
A0001	<i>Cerbera manghas</i>	Cerbera	835532	836587	0.2	0.63	7	4		1																Broken branches recorded.	
A0002	<i>Cerbera manghas</i>	Cerbera	835533	836588	0.35	1.10	9	7		1																Tree has been deheaded.	
A0157	<i>camphora</i>	Camphora Tree	835655	836811	0.25	0.79	8	6		1																Tree has grown on slope. Leaning trunk and broken branches recorded.	
A0806	<i>camphora</i>	Camphora Tree	835910	836923	0.3	0.94	12	8		1																Tree has grown on slope. Multiple trunk and broken branches recorded.	

Tree No.	Species Name Common Name		C Northing (m)	D Easting (m)	E Trunk Diameter (m)	F Trunk Circumference (m)	G Height (m)	H Crown Spread (m)	I			J			K			L			M			N			O Brief comments and description
									Tree Form			Health Condition			Amenity Value			Survival Rate after Transplantation			Conflict with Development			Proposed Treatment			
									G	F	P	G	F	P	H	M	L	H	M	L	H	M	L	Parially - Soil Nailing	Yes - New Road Alignment/ Cut Slope	No	
A1097	<i>Cinnamomum camphora</i>	Camphora Tree	836159	837038	0.35	1.10	15	10																			Tree has been recorded on concrete slope and has been attacked by termites. Tree growth has been obstructed by plants in the vicinity.
A1416	<i>camphora</i>	Camphora Tree	836428	837051	0.2	0.63	7	4																			Tree has grown on concrete slope. Multiple trunks recorded.
A1418	<i>camphora</i>	Camphora Tree	836430	837053	0.2	0.63	6	4																			Tree has grown on concrete slope and twisted by climbers.
A1478	<i>camphora</i>	Camphora Tree	836519	837010	0.2	0.63	5	3																			Tree has grown on slope. Broken and dead branches recorded.
A1480	<i>camphora</i>	Camphora Tree	836526	837012	0.32	1.00	11	3																			Tree has grown on slope. Leaning trunk recorded.
A1766	<i>camphora</i>	Camphora Tree	836771	836856	0.2	0.63	8	4																			Tree has grown on slope and twisted by climbers. Deformed trunk recorded.
A1773	<i>camphora</i>	Camphora Tree	837023	836859	0.2	0.63	4	3																			Tree has grown on slope. Deformed trunk recorded.
A0003	<i>Cinnamomum camphora</i>	Camphora Tree	835558	836591	1.5	4.71	11	8																			Tree has been mature in size. Tree growth has been obstructed by other plants in the vicinity. Broken branches recorded.
A0673	<i>camphora</i>	Camphora Tree	835807	836894	0.45	1.41	10	12																			Tree has grown on slope and is mature in size. Multiple trunk recorded.
A0674	<i>camphora</i>	Camphora Tree	835821	836890	0.3	0.94	12	10																			Tree has grown on slope and been twisted by climbers. Multiple trunks recorded.
A0775	<i>camphora</i>	Camphora Tree	835827	836890	0.35	1.10	10	9																			Tree has grown on slope and twisted by climbers. Multiple trunks recorded.
A1384	<i>Cinnamomum camphora</i>	Camphora Tree	836440	837039	0.2	0.63	7	6																			Tree has grown on slope and twisted by climbers. Tree growth has been obstructed by other plants in the vicinity. Deformed trunk recorded.
A1389	<i>Cinnamomum camphora</i>	Camphora Tree	836431	837039	0.15	0.47	6	4																			Tree has been twisted by climbers. Tree growth has been obstructed by other plants in the vicinity. Multiple trunks recorded.
A1462	<i>camphora</i>	Camphora Tree	836470	837002	0.35	1.10	12	8																			Tree has grown on slope. Broken branches recorded.
A1463	<i>camphora</i>	Camphora Tree	836483	837004	0.6	1.88	14	12																			Tree has grown on slope and twisted by climbers. Multiple trunks recorded.
A1737	<i>camphora</i>	Camphora Tree	836730	836895	0.23	0.72	7	4																			Tree has grown on slope. Multiple trunks recorded.
A1772	<i>camphora</i>	Camphora Tree	837013	836859	0.3	0.94	12	9																			Tree has grown on slope. Multiple trunks recorded.
A1551	Dead tree	--	836570	837015	0.15	0.47	4	2																			Tree has been deheaded.
A1552	Dead tree	--	836569	837015	0.15	0.47	4	1																			Tree has been deheaded.
A1460	Dead tree	--	836473	837000	0.095	0.30	5	2																			Tree has grown on slope and twisted by climbers. Leaning trunk recorded.
A1509	Dead tree	--	836542	837001	0.15	0.47	5	3																			Tree grown on slope and twisted by climbers.
A1516	Dead tree	--	836531	837000	0.15	0.47	7	2																			Tree grown on slope and twisted by climbers.
A1558	Dead tree	--	836558	837008	0.1	0.31	6	2																			Tree has died.
A1573	Dead tree	--	836577	837015	0.15	0.47	6	3																			Tree has died.
A0016	<i>Dimocarpus longan</i>	Longan	835560	836657	0.25	0.79	6	4																			Tree growth has been obstructed by other plants in the vicinity. Broken branches recorded.
A1498	<i>chinense</i>	Endospermum	836564	837013	0.17	0.53	7	4																			Deformed trunk recorded.
A1565	<i>chinense</i>	Endospermum	836589	837015	0.35	1.10	15	7																			Tree has been twisted by climbers.
A1566	<i>chinense</i>	Endospermum	836593	837014	0.2	0.63	11	6																			Tree has been twisted by climbers.
A1578	<i>chinense</i>	Endospermum	836587	837014	0.13	0.41	6	2																			Tree has been twisted by climbers. Leaning trunk recorded.
A1255	<i>chinense</i>	Endospermum	836349	837041	0.3	0.94	13	6																			Tree has grown on slope.
A1262	<i>chinense</i>	Endospermum	836342	837036	0.3	0.94	13	7																			Tree has grown on slope.
A1474	<i>chinense</i>	Endospermum	836491	837003	0.3	0.94	16	9																			Tree has grown on slope. Elongated trunk recorded.
A1506	<i>chinense</i>	Endospermum	836551	837002	0.25	0.79	12	6																			Tree grown on slope and twisted by climbers. Deformed trunk recorded.
A1577	<i>chinense</i>	Endospermum	836584	837012	0.4	1.26	15	8																			Elongated trunk recorded.
A1582	<i>chinense</i>	Endospermum	836596	837010	0.3	0.94	12	6																			Tree has been twisted by climbers. Leaning trunk recorded.
A0121	<i>Ficus hispida</i>	Opposite-leaved Fig	835631	836803	0.15	0.47	6	4																			Multiple trunks recorded.
A0669	<i>Ficus hispida</i>	Opposite-leaved Fig	835792	836892	0.2	0.63	8	5																			Tree has grown on slope. Elongated trunks and broken branches recorded.
A1776	<i>Ficus hispida</i>	Opposite-leaved Fig	837045	836849	0.2	0.63	4	4																			Tree has grown on slope. Multiple trunks recorded.
A0024	<i>Ficus microcarpa</i>	Chinese Banyan	835552	836703	0.3	0.94	5	4																			Damaged leaning trunk recorded.
A0028	<i>Ficus microcarpa</i>	Chinese Banyan	835554	836711	1.7	5.34	15	20																			Tree has been mature in size and twisted by climbers. Damaged branches
A0055	<i>Ficus variegata</i>	Common Red-stem Fig	835590	836760	0.5	1.57	10	6																			Tree has grown on slope and twisted by climbers. Multiple elongated trunks recorded.
A0357	<i>Ficus variegata</i>	Common Red-stem Fig	835677	836819	0.17	0.53	8	4																			Tree has grown on slope. Leaning trunk recorded.
A1702	<i>Ficus variegata</i>	Common Red-stem Fig	836707	836953	0.22	0.69	6	4																			Tree has grown on slope. Deformed trunk recorded.
A1385	<i>Ficus variegata</i>	Common Red-stem Fig	836444	837036	0.17	0.53	7	5																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Multiple trunks and broken branches recorded.

A	B		C	D	E	F	G	H	I			J			K			L			M			N			O								
	Tree No.	Species Name							Common Name	Northing (m)	Easting (m)	Trunk Diameter (m)	Trunk Circumference (m)	Height (m)	Crown Spread (m)	Tree Form			Health Condition			Amenity Value			Survival Rate after Transplantation			Conflict with Development			Proposed Treatment			Brief comments and description	
																G	F	P	G	F	P	H	M	L	H	M		L	H	M	L	Partially - Soil Nailing	Yes - New Road Alignment/ Cut Slope		No
A1126	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836198	837049	0.13	0.41	6	3			1		1									1			1			Tree has grown on slope. Multiple trunks recorded.							
A1299	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836393	837060	0.17	0.53	10	6			1		1									1			1			Tree has grown on slope.							
A1545	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836585	837023	0.15	0.47	7	5			1		1									1			1			Tree has grown on slope. Multiple trunks recorded.							
A1148	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836264	837077	0.15	0.47	6	4			1		1											1		1		Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Multiple trunk recorded.							
A1150	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836262	837077	0.15	0.47	5	4			1		1											1		1		Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.							
A1301	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836365	837045	0.2	0.63	8	6			1		1													1		Tree has grown on slope. Multiple trunks recorded.							
A1370	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836418	837044	0.17	0.53	9	6			1		1													1		Tree has grown on slope and infected by fungi. Broken branches recorded.							
A1371	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836419	837044	0.23	0.72	15	8			1		1													1		Tree has grown on slope.							
A1433	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836454	837026	0.23	0.72	9	3			1		1													1		Tree has grown on slope and twisted by climbers.							
A1437	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836460	837019	0.1	0.31	5	2			1		1													1		Tree grows on slope, is twisted by climbers and is obstructed to grow by other							
A1438	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836459	837018	0.2	0.63	10	3			1		1													1		Tree grows on slope and is obstructed to grow by other plants.							
A1439	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836460	837017	0.17	0.53	10	6			1		1													1		Tree has multiple trunk and grows on slope.							
A1465	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836498	837007	0.17	0.53	6	3			1		1													1		Tree has grown on slope and twisted by climbers.							
A1512	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836538	837000	0.2	0.63	8	4			1		1												1		1	Tree has grown on slope. Broken branches and leaning trunk recorded.							
A1530	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836512	837000	0.17	0.53	8	4			1		1													1		Tree has grown on slope and twisted by climbers. Multiple trunks recorded.							
A1531	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836516	837003	0.17	0.53	10	3			1		1													1		Tree has grown on slope. Multiple trunks recorded. Tree growth has been obstructed by other plants in the vicinity.							
A1532	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836517	837002	0.13	0.41	10	3			1		1													1		Tree has grown on slope. Tree growth has been obstructed by other plants in the							
A1584	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836601	837007	0.2	0.63	14	6			1		1													1		Tree has been twisted by climbers.							
A1621	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836644	836969	0.17	0.53	6	4			1		1												1		1	Tree has grown on slope. Elongated trunk recorded.							
A1659	<i>Garcinia oblongifolia</i>	Lingnan Garcinia	836658	836965	0.15	0.47	5	4			1		1													1		Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.							
A1708	<i>Glochidion macrophylla</i>	Large-leaved Abacus Plant	836710	836937	0.17	0.53	4	2			1		1													1		Deformed trunk recorded.							
A1771	<i>Glochidion macrophylla</i>	Large-leaved Abacus Plant	837011	836868	0.17	0.53	2	2			1		1													1		Tree has grown on slope. Deformed trunk recorded.							
A1614	<i>Glochidion zeylanicum</i>	Hong Kong Abacus Plant	836643	836973	0.15	0.47	4	2			1		1													1		Multiple broken trunks recorded..							
A1688	<i>Glochidion zeylanicum</i>	Hong Kong Abacus Plant	836664	836959	0.13	0.41	4	3			1		1													1		Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.							
A1025	<i>Helicia cochinchinensis</i>	Cochin-china Helicia																								1		1							
A0004	<i>leucocephala</i>	White Popinac	835568	836588	0.15	0.47	5	3			1		1													1		1	Tree has grown on slope.						
A0005	<i>leucocephala</i>	White Popinac	835568	836587	0.15	0.47	8	6			1		1													1		1	Tree has grown on slope.						
A2036	<i>leucocephala</i>	White Popinac	836218	837067	0.13	0.41	8	5			1		1													1		1	Tree has been twisted by climbers. Tree has been recorded on concrete slope.						
A0111	<i>Litsea cubeba</i>	Fragrant Litsea	835593	836765	0.2	0.63	6	3			1		1													1		1	Tree has grown on slope. Elongated trunks recorded.						
A1481	<i>Litsea cubeba</i>	Fragrant Litsea	836526	837012	0.18	0.57	6	4			1		1													1		1	Tree has grown on slope. Leaning trunk recorded.						
A0416	<i>Lophostemon conferta</i>	Brisbane Box	835691	836831	0.5	1.57	15	7			1		1													1		1	Tree has grown on slope.						
A0780	<i>Lophostemon conferta</i>	Brisbane Box	835849	836902	0.3	0.94	13	7			1		1													1		1	Multiple trunks recorded.						
A0978	<i>Lophostemon conferta</i>	Brisbane Box	836025	836932	0.35	1.10	12	7			1		1													1		1	Tree has grown on slope.						
A0979	<i>Lophostemon conferta</i>	Brisbane Box	836026	836932	0.15	0.47	10	4			1		1													1		1	Tree has grown on slope. Multiple leaning trunks recorded.						
A1078	<i>Lophostemon conferta</i>	Brisbane Box	836109	837040	0.35	1.10	13	6			1		1													1		1	Tree has grown on concrete slope. Broken branches recorded.						
A1086	<i>Lophostemon conferta</i>	Brisbane Box	836097	837037	0.5	1.57	12	7			1		1													1		1	Tree has been twisted by climbers. Leaning trunk recorded.						
A0025	<i>Macaranga tanarius</i>	Elephant's Ear	835555	836704	0.2	0.63	4	4			1		1													1		1	Tree growth has been obstructed by other plants in the vicinity and twisted by climbers. Broken branches and leaning trunks recorded.						
A0068	<i>Macaranga tanarius</i>	Elephant's Ear	835611	836781	0.2	0.63	5	5			1		1													1		1	Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Leaning trunk recorded.						
A0038	<i>Machilus breviflora</i>	Short-flowered Machilus	835581	836751	0.15	0.47	6	2			1		1													1		1	Tree has grown on slope and twisted by climbers. Leaning trunk recorded.						
A0057	<i>Machilus breviflora</i>	Short-flowered Machilus	835586	836755	0.15	0.47	6	4			1		1													1		1	Tree has grown on slope. Tree growth have been obstructed by other plants in the vicinity.						

A Tree No.	B Species Name Common Name		C Northing (m)	D Easting (m)	E Trunk Diameter (m)	F Trunk Circumference (m)	G Height (m)	H Crown Spread (m)	I Tree Form			J Health Condition			K Amenity Value			L Survival Rate after Transplantation			M Conflict with Development			N Proposed Treatment			O Brief comments and description
	G	F	P	G	F	P	H	M	L	H	M	L	Paritally - Soil Nailing	Yes - New Road Alignment/ Cut Slope	No	Fell	Retain	Transplant									
A0102	<i>Machilus breviflora</i>	Short-flowered Machilus	835603	836781	0.15	0.47	6	4			1	1			1		1									Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Leaning trunk recorded.	
A1379	<i>Machilus breviflora</i>	Short-flowered Machilus	836433	837040	0.15	0.47	7	2			1	1			1			1								Tree has grown on slope and twisted by climbers. Tree growth has been obstructed by other plants in the vicinity. Multiple trunks recorded.	
A1611	<i>Machilus breviflora</i>	Short-flowered Machilus	836631	836984	0.2	0.63	8	6			1	1			1			1								Elongated trunk and broken branches recorded..	
A1617	<i>Machilus breviflora</i>	Short-flowered Machilus	836650	836970	0.2	0.63	10	6			1	1			1			1								Tree has grown on slope. Elongated trunk recorded.	
A1646	<i>Machilus breviflora</i>	Short-flowered Machilus	836651	836970	0.22	0.69	10	6			1	1			1			1								Tree has grown on slope. Elongated trunk recorded.	
A1678	<i>Machilus breviflora</i>	Short-flowered Machilus	836673	836952	0.13	0.41	5	2			1	1			1			1								Tree has grown on slope. Leaning trunk recorded.	
A0122	<i>Mallotus paniculatus</i>	Turn-in-the-wind	835630	836803	0.2	0.63	6	5			1	1			1			1								Elongated trunk and broken branches recorded.	
A0287	<i>Mallotus paniculatus</i>	Turn-in-the-wind	835636	836805	0.15	0.47	6	4			1	1			1			1								Tree has been twisted by climbers and grown on slope. Leaning trunk and broken branches recorded.	
A0802	<i>Melia azedarach</i>	China-berry	835846	836897	0.12	0.38	7	1.5			1	1			1			1								Tree has grown on slope. Elongated trunk and broken branches recorded.	
A0916	<i>Melia azedarach</i>	China-berry	835996	836940	0.2	0.63	7	2			1	1			1			1								Tree has grown on slope. Elongated trunk recorded.	
A0036	<i>Microcos paniculata</i>	Microcos	835578	836749	0.15	0.47	7	4			1	1			1			1								Tree has grown on slope. Multiple leaning trunks recorded.	
A0865	<i>Mussaenda pubescens</i>	Splash-of-white	835971	836927	0.15	0.47	7	2			1	1			1			1								Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Leaning trunk and broken branches recorded.	
A1686	<i>Phyllanthus emblica</i>	Myrobalan	836665	836955	0.12	0.38	5	2			1				1			1	1							Tree has grown on slope.	
A1687	<i>Phyllanthus emblica</i>	Myrobalan	836664	836957	0.15	0.47	5	3			1				1			1	1							Tree has grown on slope.	
A1719	<i>Phyllanthus emblica</i>	Myrobalan	836711	836915	0.2	0.63	3	4			1	1			1			1								Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.	
A1768	<i>Phyllanthus emblica</i>	Myrobalan	836975	836848	0.2	0.63	2	2			1	1			1			1								Tree has grown on slope and twisted by climbers. Deformed leaning trunk	
A1774	<i>Phyllanthus emblica</i>	Myrobalan	837029	836852	0.1	0.31	4	2			1	1			1			1								Tree growth has been obstructed by other plants in the vicinity. Leaning trunk	
A1222	<i>Pinus elliptii</i>	Slash Pine (Burnt)	836329	837051	0.3	0.94	12	5			1	1			1			1								Tree has been in healthy condition.	
A1223	<i>Pinus elliptii</i>	Slash Pine(Burnt)	836329	837053	0.2	0.63	12	3			1	1			1			1								Broken branches recorded.	
A1225	<i>Pinus elliptii</i>	Slash Pine(Burnt)	836331	837052	0.2	0.63	11	3			1	1			1			1								Broken branches recorded.	
A1230	<i>Pinus elliptii</i>	Slash Pine(Burnt)	836338	837050	0.23	0.72	11	4			1	1			1			1								Broken branches recorded.	
A1231	<i>Pinus elliptii</i>	Slash Pine(Burnt)	836338	837049	0.3	0.94	13	6			1	1			1			1								Tree has been in healthy condition.	
A1232	<i>Pinus elliptii</i>	Slash Pine(Burnt)	836342	837050	0.2	0.63	10	3			1	1			1			1								Elongated trunk recorded.	
A1281	<i>Pinus elliptii</i>	Slash Pine(Burnt)	836347	837051	0.2	0.63	11	3			1	1			1			1								Elongated trunk recorded.	
A1282	<i>Pinus elliptii</i>	Slash Pine(Burnt)	836348	837050	0.2	0.63	11	3			1	1			1			1								Elongated trunk recorded.	
A1283	<i>Pinus elliptii</i>	Slash Pine(Burnt)	836350	837053	0.2	0.63	11	3			1	1			1			1								Elongated trunk recorded.	
A1284	<i>Pinus elliptii</i>	Slash Pine(Burnt)	836348	837053	0.15	0.47	11	2			1	1			1			1								Elongated trunk recorded.	
A1287	<i>Pinus elliptii</i>	Slash Pine	836355	837053	0.13	0.41	5	4			1	1			1			1								Tree has been in healthy condition.	
A1292	<i>Pinus elliptii</i>	Slash Pine(Burnt)	836373	837060	0.23	0.72	10	6			1	1			1			1								Tree has been in healthy condition.	
A1298	<i>Pinus elliptii</i>	Slash Pine	836391	837062	0.2	0.63	12	5			1	1			1			1								Tree has grown on slope.	
A1350	<i>Pinus elliptii</i>	Slash Pine(Dead)	836394	837062	0.17	0.53	8	3			1	1			1			1								Leaning elongated trunk recorded.	
A1355	<i>Pinus elliptii</i>	Slash Pine	836409	837058	0.3	0.94	11	6			1	1			1			1								Tree has grown on slope.	
A1764	<i>Rhus succedanea</i>	Wax Tree	836762	836853	0.17	0.53	6	3			1	1			1			1								Tree has grown on slope and twisted by climbers. Tree growth has been obstructed by other plants in the vicinity.	
A0035	<i>Schefflera heptaphylla</i>	Ivy Tree	835573	836743	0.4	1.26	7	4			1	1			1			1								Tree has grown on slope and twisted by climbers. Leaning trunk recorded.	
A0405	<i>Schefflera heptaphylla</i>	Ivy Tree	835679	836823	0.17	0.53	5	4			1	1			1			1								Tree has grown on slope.	
A0781	<i>Schefflera heptaphylla</i>	Ivy Tree	835849	836899	0.16	0.50	6	5			1	1			1			1								Tree has grown on slope and twisted by climbers. Multiple trunks recorded.	
A0783	<i>Schefflera heptaphylla</i>	Ivy Tree	835858	836905	0.17	0.53	6	3			1	1			1			1								Tree has grown on slope and twisted by climbers. Elongated leaning trunk	
A0787	<i>Schefflera heptaphylla</i>	Ivy Tree	835861	836908	0.23	0.72	7	6			1	1			1			1								Tree has grown on slope. Leaning trunk recorded.	
A0791	<i>Schefflera heptaphylla</i>	Ivy Tree	835863	836909	0.15	0.47	5	4			1	1			1			1								Tree has grown on slope. Leaning trunk recorded.	
A0793	<i>Schefflera heptaphylla</i>	Ivy Tree	835867	836912	0.15	0.47	4	3			1	1			1			1								Tree has grown on slope. Tree growth has been obstructed by other plants.	
A0794	<i>Schefflera heptaphylla</i>	Ivy Tree	835868	836912	0.1	0.31	6	4			1	1			1			1								Tree has grown on slope and twisted by climbers.	
A0795	<i>Schefflera heptaphylla</i>	Ivy Tree	835868	836912	0.2	0.63	6	4			1	1			1			1								Tree has grown on slope and twisted by climbers.	
A0931	<i>Schefflera heptaphylla</i>	Ivy Tree	836009	836922	0.15	0.47	4	2			1	1			1			1								Tree has grown on slope. Multiple elongated trunks recorded.	

A Tree No.	B		C Northing (m)	D Easting (m)	E Trunk Diameter (m)	F Trunk Circumference (m)	G Height (m)	H Crown Spread (m)	I			J			K			L			M			N			O Brief comments and description
	Species Name	Common Name							Tree Form	Health Condition			Amenity Value			Survival Rate after Transplantation			Conflict with Development			Proposed Treatment					
										G	F	P	G	F	P	H	M	L	H	M	L	Paritally - Soil Nailing	Yes - New Road Alignment/ Cut Slope	No	Fell	Retain	
A0105	Schima superba	Schima	835601	836778	0.4	1.26	14	8		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0113	Schima superba	Schima	835608	836788	0.3	0.94	15	5		1	1			1		1				1		1					Tree has grown on slope. Elongated trunks recorded.
A0118	Schima superba	Schima	835610	836794	0.4	1.26	13	6		1	1			1		1				1		1					Tree has grown on slope. Multiple elongated trunks recorded.
A0125	Schima superba	Schima	835619	836802	0.3	0.94	10	6		1	1			1		1				1		1					Tree has been twisted by climbers and grown on slope.
A0152	Schima superba	Schima	835641	836806	0.15	0.47	6	2		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0153	Schima superba	Schima	835642	836807	0.17	0.53	7	2		1	1			1		1				1		1					Tree has grown on slope. Leaning trunk recorded.
A0154	Schima superba	Schima	835644	836808	0.15	0.47	7	3		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0155	Schima superba	Schima	835649	836808	0.15	0.47	6	2		1	1			1		1				1		1					Tree has grown on slope. Leaning trunk and broken branches recorded.
A0156	Schima superba	Schima	835650	836809	0.2	0.63	8	4		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0453	Schima superba	Schima	835696	836841	0.15	0.47	8	5		1	1			1		1				1		1					Elongated trunk recorded.
A0507	Schima superba	Schima	835725	836852	0.35	1.10	13	7		1	1			1		1				1		1					Tree has grown on slope. Elongated trunk recorded.
A0508	Schima superba	Schima	835723	836852	0.3	0.94	15	7		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0509	Schima superba	Schima	835721	836850	0.21	0.66	14	8		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0510	Schima superba	Schima	835721	836849	0.25	0.79	13	8		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0625	Schima superba	Schima	835726	836853	0.2	0.63	12	4		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks and broken branches recorded.
A0630	Schima superba	Schima	835732	836855	0.5	1.57	14	12		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks and broken branches recorded.
A0634	Schima superba	Schima	835735	836858	0.25	0.79	12	8		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks and broken branches recorded.
A0635	Schima superba	Schima	835739	836860	0.22	0.69	14	7		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0636	Schima superba	Schima	835742	836862	0.35	1.10	14	8		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0645	Schima superba	Schima	835745	836867	0.3	0.94	12	6		1	1			1		1				1		1					Tree has been twisted by climbers and grown on slope. Multiple trunks recorded.
A0656	Schima superba	Schima	835750	836872	0.15	0.47	6	3		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0658	Schima superba	Schima	835749	836870	0.17	0.53	8	3		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0660	Schima superba	Schima	835748	836869	0.15	0.47	6	2		1	1			1		1				1		1					Tree has grown on slope. Elongated trunks recorded.
A0661	Schima superba	Schima	835753	836872	0.2	0.63	14	4		1	1			1		1				1		1					Tree has grown on slope. Elongated trunks recorded.
A0684	Schima superba	Schima	835766	836877	0.25	0.79	13	6		1	1			1		1				1		1					Tree has grown on slope. Elongated trunk recorded.
A0691	Schima superba	Schima	835768	836878	0.15	0.47	13	7		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0692	Schima superba	Schima	835770	836880	0.25	0.79	13	7		1	1			1		1				1		1					Tree have grown on slope.
A0701	Schima superba	Schima	835774	836883	0.2	0.63	9	6		1	1			1		1				1		1					Tree has been twisted by climbers and grown on slope. Multiple trunks recorded.
A0702	Schima superba	Schima	835775	836885	0.3	0.94	13	7		1	1			1		1				1		1					Tree has been twisted by climbers and grown on slope. Multiple trunks recorded.
A0705	Schima superba	Schima	835777	836887	0.25	0.79	11	9		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0713	Schima superba	Schima	835786	836901	0.3	0.94	14	8		1	1			1		1				1		1					Tree has grown on slope and is mature in size. Multiple trunks recorded.
A0714	Schima superba	Schima	835786	836900	0.25	0.79	12	7		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0715	Schima superba	Schima	835791	836901	0.25	0.79	14	8		1	1			1		1				1		1					Tree has been twisted by climbers and grown on slope. Multiple trunks recorded.
A0733	Schima superba	Schima	835765	836877	0.15	0.47	7	4		1	1			1		1				1		1					Tree has grown on slope. Elongated trunk recorded.
A0734	Schima superba	Schima	835764	836876	0.15	0.47	7	3		1	1			1		1				1		1					Tree has grown on slope. Multiple elongated trunks recorded.
A0735	Schima superba	Schima	835763	836875	0.15	0.47	12	4		1	1			1		1				1		1					Tree has grown on slope. Multiple elongated trunks recorded.
A0736	Schima superba	Schima	835762	836876	0.15	0.47	14	4		1	1			1		1				1		1					Tree has grown on slope. Multiple leaning trunks recorded.
A0737	Schima superba	Schima	835762	836874	0.21	0.66	13	5		1	1			1		1				1		1					Tree has grown on slope. Multiple leaning trunks recorded.
A0738	Schima superba	Schima	835760	836874	0.2	0.63	13	3		1	1			1		1				1		1					Tree has grown on slope. Leaning trunk recorded.
A0739	Schima superba	Schima	835759	836874	0.15	0.47	12	3		1	1			1		1				1		1					Tree has grown on slope. Elongated trunk recorded.
A0740	Schima superba	Schima	835759	836875	0.15	0.47	8	1		1	1			1		1				1		1					Tree has grown on slope. Elongated trunk recorded.
A0741	Schima superba	Schima	835758	836873	0.2	0.63	10	2		1	1			1		1				1		1					Tree has grown on slope. Elongated trunk recorded.
A0742	Schima superba	Schima	835758	836872	0.2	0.63	9	5		1	1			1		1				1		1					Tree has grown on slope. Multiple leaning trunk recorded.
A0743	Schima superba	Schima	835756	836872	0.3	0.94	12	6		1	1			1		1				1		1					Tree has grown on slope. Elongated trunk recorded.
A0744	Schima superba	Schima	835755	836874	0.15	0.47	10	3		1	1			1		1				1		1					Tree has grown on slope. Elongated trunk recorded.
A0752	Schima superba	Schima	835891	836921	0.2	0.63	10	5		1	1			1		1				1		1					Tree has grown on slope and twisted by climbers. Multiple trunks recorded.
A0753	Schima superba	Schima	835892	836920	0.2	0.63	10	5		1	1			1		1				1		1					Tree has grown on slope and twisted by climbers.
A0786	Schima superba	Schima	835860	836908	0.25	0.79	12	6		1	1			1		1				1		1					Tree has grown on slope. Broken branches and leaning trunk recorded.
A0798	Schima superba	Schima	835873	836918	0.25	0.79	7	5		1	1			1		1				1		1					Tree has grown on slope. Multiple trunks recorded.
A0824	Schima superba	Schima	835916	836931	0.2	0.63	6	3		1	1			1		1				1		1					Tree has grown on slope. Broken branches recorded.
A0827	Schima superba	Schima	835909	836931	0.5	1.57	10	7		1	1			1		1				1		1					Tree has grown on slope. Multiple trunk and broken branches recorded.
A0830	Schima superba	Schima	835903	836929	0.23	0.72	10	5		1	1			1		1				1		1					Tree has grown on slope. Multiple trunk recorded.
A0832	Schima superba	Schima	835901	836929	0.2	0.63	10	6		1	1			1		1				1		1					Tree has grown on slope. Multiple trunk and broken branches recorded.

A Tree No.	B		C Northing (m)	D Easting (m)	E Trunk Diameter (m)	F Trunk Circumference (m)	G Height (m)	H Crown Spread (m)	I			J			K			L			M			N			O Brief comments and description
	Species Name								Common Name	Tree Form	Health Condition			Amenity Value			Survival Rate after Transplantation			Conflict with Development			Proposed Treatment				
											G	F	P	G	F	P	H	M	L	H	M	L	Paritally - Soil Nailing	Yes - New Road Alignment/ Cut Slope	No	Fell	
A1118	<i>Schima superba</i>	Schima	836174	837041	0.3	0.94	15	12			1	1			1			1			1						Multiple elongated trunks have been recorded. Tree has been recorded on concrete slope. Tree growth has been obstructed by plants in the vicinity.
A1119	<i>Schima superba</i>	Schima	836180	837041	0.25	0.79	12	8			1	1			1			1			1						Multiple elongated trunks have been recorded. Tree growth has been obstructed by plants in the vicinity.
A1120	<i>Schima superba</i>	Schima	836184	837042	0.25	0.79	15	12			1	1			1			1			1						Tree has grown on concrete slope. Multiple trunks recorded.
A1122	<i>Schima superba</i>	Schima	836191	837043	0.17	0.53	6	4			1		1					1			1						Tree has been twisted by climbers and recorded on concrete slope. Tree growth has been obstructed by plants in the vicinity. Tree has been recorded of nearly
A1125	<i>Schima superba</i>	Schima	836195	837046	0.15	0.47	6	5			1	1			1			1			1						Tree has grown on slope and twisted by climbers.
A1127	<i>Schima superba</i>	Schima	836201	837053	0.3	0.94	12	8			1	1			1			1			1						Tree has grown on slope and twisted by climbers. Multiple trunks recorded.
A1128	<i>Schima superba</i>	Schima	836203	837055	0.3	0.94	12	8			1	1			1			1			1						Tree has grown on slope and twisted by climbers. Multiple trunks recorded.
A1129	<i>Schima superba</i>	Schima	836203	837059	0.2	0.63	6	3			1	1			1			1			1						Tree has grown on slope and twisted by climbers. Multiple trunks recorded.
A1130	<i>Schima superba</i>	Schima	836201	837060	0.2	0.63	6	4			1	1			1			1			1						Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.
A1131	<i>Schima superba</i>	Schima	836239	837076	0.2	0.63	6	4			1	1			1			1			1						Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Damaged trunk recorded.
A1342	<i>Schima superba</i>	Schima	836403	837057	0.17	0.53	7	3			1	1			1			1			1						Tree has grown on slope. Elongated trunk recorded.
A1343	<i>Schima superba</i>	Schima	836401	837058	0.17	0.53	7	2			1	1			1			1			1						Tree has grown on slope. Elongated trunk recorded.
A1344	<i>Schima superba</i>	Schima	836399	837058	0.15	0.47	7	4			1	1			1			1			1						Tree has grown on slope. Multiple trunks recorded.
A1354	<i>Schima superba</i>	Schima	836405	837059	0.17	0.53	8	4			1	1			1			1			1						Tree has grown on slope.
A1356	<i>Schima superba</i>	Schima	836402	837051	0.17	0.53	8	3			1		1		1			1			1						Tree has grown on slope and twisted by climbers. Leaning trunk recorded.
A1357	<i>Schima superba</i>	Schima	836403	837051	0.3	0.94	12	8			1	1			1			1			1						Tree has grown on slope and twisted by climbers. Multiple trunks recorded.
A1414	<i>Schima superba</i>	Schima	836423	837053	0.35	1.10	8	7			1	1			1			1			1						Tree has grown on concrete slope. Multiple trunks recorded.
A1415	<i>Schima superba</i>	Schima	836426	837051	0.15	0.47	6	4			1	1			1			1			1						Tree has grown on concrete slope. Multiple trunks recorded.
A1422	<i>Schima superba</i>	Schima	836436	837050	0.12	0.38	6	3			1	1			1			1			1						Tree has grown on concrete slope. Multiple trunks recorded.
A1423	<i>Schima superba</i>	Schima	836435	837052	0.2	0.63	9	6			1	1			1			1			1						Tree has grown on concrete slope. Multiple trunks recorded.
A1424	<i>Schima superba</i>	Schima	836440	837049	0.15	0.47	5	4			1	1			1			1			1						Tree has grown on concrete slope. Multiple trunks recorded.
A1428	<i>Schima superba</i>	Schima	836446	837047	0.22	0.69	8	5			1	1			1			1			1						Tree has grown on concrete slope. Multiple trunks recorded.
A1486	<i>Schima superba</i>	Schima	836521	837005	0.4	1.26	15	12			1	1			1			1			1						Tree has grown on slope. Multiple trunks recorded.
A1501	<i>Schima superba</i>	Schima	836549	837016	0.22	0.69	8	4			1	1			1			1			1						Tree has grown on slope.
A1502	<i>Schima superba</i>	Schima	836556	837017	0.2	0.63	6	3			1	1			1			1			1						Tree has grown on slope.
A1504	<i>Schima superba</i>	Schima	836564	837018	0.15	0.47	5	3			1	1			1			1			1						Tree has grown on slope. Leaning trunk recorded.
A1505	<i>Schima superba</i>	Schima	836566	837018	0.2	0.63	7	4			1	1			1			1			1						Tree has grown on slope.
A1533	<i>Schima superba</i>	Schima	836562	837019	0.17	0.53	6	2			1	1			1			1			1						Tree has grown on slope.
A1534	<i>Schima superba</i>	Schima	836563	837021	0.15	0.47	5	3			1	1			1			1			1						Tree has grown on slope.
A1535	<i>Schima superba</i>	Schima	836562	837021	0.2	0.63	6	3			1	1			1			1			1						Tree has grown on slope.
A1536	<i>Schima superba</i>	Schima	836567	837020	0.15	0.47	9	4			1	1			1			1			1						Tree has grown on slope. Multiple trunks recorded.
A1537	<i>Schima superba</i>	Schima	836567	837022	0.17	0.53	8	4			1	1			1			1			1						Tree has grown on slope. Multiple trunks recorded.
A1538	<i>Schima superba</i>	Schima	836574	837023	0.15	0.47	6	3			1	1			1			1			1						Elongated trunk recorded.
A1539	<i>Schima superba</i>	Schima	836575	837024	0.15	0.47	6	4			1	1			1			1			1						Tree has grown on slope.
A1547	<i>Schima superba</i>	Schima	836589	837022	0.2	0.63	7	4			1	1			1			1			1						Multiple trunks recorded.
A1549	<i>Schima superba</i>	Schima	836573	837017	0.12	0.38	5	1			1	1			1			1			1						Tree has been twisted by climbers.
A1550	<i>Schima superba</i>	Schima	836572	837016	0.2	0.63	6	1.5			1	1			1			1			1						Tree has been twisted by climbers.
A1560	<i>Schima superba</i>	Schima	836580	837017	0.17	0.53	9	3			1	1			1			1			1						Elongated leaning trunk recorded.
A1561	<i>Schima superba</i>	Schima	836582	837017	0.3	0.94	13	8			1	1			1			1			1						Elongated leaning trunk recorded.
A1568	<i>Schima superba</i>	Schima	836597	837011	0.3	0.94	12	10			1		1		1			1			1						Tree has been twisted by climbers.
A1572	<i>Schima superba</i>	Schima	836593	837021	0.17	0.53	6	5			1	1			1			1			1						Multiple trunks recorded.
A1597	<i>Schima superba</i>	Schima	836610	837006	0.2	0.63	12	5			1	1			1			1			1						Multiple elongated trunks recorded.
A1598	<i>Schima superba</i>	Schima	836611	837012	0.2	0.63	7	4			1	1			1			1			1						Tree has grown on slope.
A1599	<i>Schima superba</i>	Schima	836616	837011	0.18	0.57	6	5			1	1			1			1			1						Tree has grown on slope. Multiple trunks recorded.
A1600	<i>Schima superba</i>	Schima	836606	837016	0.15	0.47	5	4			1	1			1			1			1						Multiple trunks recorded.
A1601	<i>Schima superba</i>	Schima	836605	837017	0.15	0.47	6	2			1	1			1			1			1						Elongated trunk recorded.
A1602	<i>Schima superba</i>	Schima	836604	837017	0.12	0.38	5	3			1	1			1			1			1						Multiple trunks recorded.
A1603	<i>Schima superba</i>	Schima	836601	837019	0.15	0.47	5	3			1	1			1			1			1						Elongated trunk recorded.

A	B		C	D	E	F	G	H	I			J			K			L			M			N			O	
	Tree No.	Species Name	Common Name	Northing (m)	Easting (m)	Trunk Diameter (m)	Trunk Circumference (m)	Height (m)	Crown Spread (m)	Tree Form			Health Condition			Amenity Value			Survival Rate after Transplantation			Conflict with Development			Proposed Treatment			Brief comments and description
										G	F	P	G	F	P	H	M	L	H	M	L	Paritally - Soil Nailing	Yes - New Road Alignment/ Cut Slope	No	Fell	Retain	Transplant	
A1604	Schima superba	Schima	836599	837019	0.15	0.47	4	2			1		1										1					Tree has grown on slope. Deformed trunk recorded.
A1607	Schima superba	Schima	836631	836997	0.17	0.53	5	4			1		1										1					Tree has grown on slope. Multiple trunks recorded.
A1703	Schima superba	Schima	836708	836954	0.22	0.69	7	4			1		1										1					Tree growth has been obstructed by other plants in the vicinity. Deformed trunk recorded.
A1707	Schima superba	Schima	836708	836953	0.23	0.72	8	5			1		1										1					Tree has grown on slope. Deformed trunk recorded.
A1725	Schima superba	Schima	836726	836915	0.15	0.47	6	5			1		1										1					Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.
A1727	Schima superba	Schima	836730	836908	0.2	0.63	5	4			1		1										1					Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.
A1728	Schima superba	Schima	836731	836906	0.1	0.31	4	3			1		1										1					Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.
A1739	Schima superba	Schima	836742	836900	0.15	0.47	5	4			1		1										1					Tree has grown on slope.
A1765	Schima superba	Schima	836771	836858	0.28	0.88	8	5			1		1										1					Tree has grown on slope and twisted by climbers. Tree growth has been obstructed by other plants in the vicinity.
A2012	Schima superba	Schima	836150	837032	0.11	0.35	5	2			1		1										1					Two main trunks have been recorded. Tree has been recorded on concrete slope and elongated trunk recorded. Tree has been twisted by climbers.
A2013	Schima superba	Schima	836149	837032	0.15	0.47	6	2			1		1										1					Elongated trunk has been recorded. Tree has been recorded on concrete slope.
A2014	Schima superba	Schima	836152	837032	0.15	0.47	8	2			1		1										1					Two elongated trunks have been recorded. Tree has been recorded on concrete
A2015	Schima superba	Schima	836153	837034	0.18	0.57	10	4			1		1										1					Two elongated trunks have been recorded. Tree has been recorded on concrete
A2022	Schima superba	Schima	836159	837034	0.11	0.35	8	3			1		1										1					Two main trunks have been recorded. Tree has been recorded on concrete
A2024	Schima superba	Schima	836159	837036	0.14	0.44	8	3			1		1										1					Tree growth has been obstructed by plants in the vicinity. Elongated trunk has been recorded. Tree has been recorded on concrete slope.
A2025	Schima superba	Schima	836157	837036	0.14	0.44	7	4			1		1										1					Two main trunks have been recorded. Tree has been recorded on concrete
A2026	Schima superba	Schima	836154	837035	0.13	0.41	8	4			1		1										1					Two elongated trunks have been recorded. Tree has been recorded on concrete
A2034	Schima superba	Schima	836175	837040	0.11	0.35	8	4			1		1										1					Elongated trunk has been recorded. Tree has been recorded on concrete slope.
A2040	Schima superba	Schima	836188	837040	0.21	0.66	8	5			1		1										1					Elongated trunk has been recorded. Tree has been recorded on concrete slope.
A2041	Schima superba	Schima	836187	837040	0.13	0.41	10	6			1		1										1					Elongated trunk has been recorded. Tree has been recorded on concrete slope.
A2045	Schima superba	Schima	836198	837046	0.1	0.38	7	4			1		1										1					Tree has been twisted by climbers. Elongated trunk has been recorded.
A0526	Schima superba	Schima	835741	836852	0.4	1.26	12	6			1		1										1			1	1	Tree has been twisted by climbers and grown on slope. Elongated trunk recorded.
A0529	Schima superba	Schima	835749	836859	0.23	0.72	11	6			1		1										1			1	1	Tree has grown on slope. Multiple trunks recorded.
A0530	Schima superba	Schima	835751	836861	0.22	0.69	12	6			1		1										1			1	1	Tree has grown on slope. Multiple leaning trunks recorded.
A0531	Schima superba	Schima	835755	836861	0.35	1.10	11	6			1		1										1			1	1	Tree has grown on slope. Leaning trunk recorded.
A0532	Schima superba	Schima	835755	836863	0.4	1.26	12	6			1		1										1			1	1	Tree has been twisted by climbers and grown on slope. Multiple elongated trunks recorded.
A0655	Schima superba	Schima	835749	836872	0.17	0.53	8	3			1		1										1			1	1	Tree has grown on slope. Elongated trunks recorded.
A0659	Schima superba	Schima	835747	836871	0.2	0.63	5	2			1		1										1			1	1	Tree has grown on slope. Elongated trunks recorded.
A0670	Schima superba	Schima	835795	836894	0.4	1.26	9	5			1		1										1			1	1	Tree has grown on slope. Leaning trunk recorded.
A0862	Schima superba	Schima	835966	836923	0.25	0.79	8	6			1		1										1			1	1	Tree has grown on slope. Leaning trunk and broken branches recorded.
A0863	Schima superba	Schima	835967	836924	0.15	0.47	7	4			1		1										1			1	1	Tree has grown on slope. Elongated trunk recorded.
A0864	Schima superba	Schima	835968	836925	0.15	0.47	6	3			1		1										1			1	1	Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Leaning trunk recorded.
A0868	Schima superba	Schima	835991	836932	0.3	0.94	14	10			1		1										1			1	1	Tree has grown on slope and twisted by climbers. Multiple trunks recorded.
A0923	Schima superba	Schima	836000	836925	0.2	0.63	7	6			1		1										1			1	1	Tree has grown on slope. Elongated trunk recorded.
A0929	Schima superba	Schima	836007	836920	0.17	0.53	7	4			1		1										1			1	1	Tree has grown on slope. Multiple elongated trunks recorded.
A0930	Schima superba	Schima	836009	836920	0.17	0.53	6	4			1		1										1			1	1	Tree has grown on slope. Multiple elongated trunks recorded.
A0935	Schima superba	Schima	836012	836919	0.15	0.47	6	4			1		1										1			1	1	Tree has grown on slope. Multiple trunks recorded.
A0936	Schima superba	Schima	836015	836918	0.17	0.53	8	6			1		1										1			1	1	Tree has grown on slope. Multiple leaning trunks recorded.
A0938	Schima superba	Schima	836017	836918	0.17	0.53	8	5			1		1										1			1	1	Tree has grown on slope. Elongated trunk recorded.
A0939	Schima superba	Schima	836020	836918	0.2	0.63	7	5			1		1										1			1	1	Tree has grown on slope. Elongated trunk recorded.
A0940	Schima superba	Schima	836022	836918	0.4	1.26	8	3			1		1										1			1	1	Tree has grown on slope. Elongated trunk recorded.
A0941	Schima superba	Schima	836028	836919	0.4	1.26	11	8			1		1										1			1	1	Tree had grown on slope and twisted by climbers.
A0946	Schima superba	Schima	836034	836919	0.3	0.94	12	6			1		1										1			1	1	Tree has grown on slope. Elongated trunk recorded.
A0947	Schima superba	Schima	836034	836920	0.25	0.79	12	4			1		1										1			1	1	Tree has grown on slope. Elongated trunk recorded.

A Tree No.	B Species Name Common Name		C Northing (m)	D Easting (m)	E Trunk Diameter (m)	F Trunk Circumference (m)	G Height (m)	H Crown Spread (m)	I Tree Form			J Health Condition			K Amenity Value			L Survival Rate after Transplantation			M Conflict with Development			N Proposed Treatment			O Brief comments and description
	G	F	P	G	F	P	H	M	L	H	M	L	Paritally - Soil Nailing	Yes - New Road Alignment/ Cut Slope	No	Fell	Retain	Transplant									
A0949	<i>Schima superba</i>	Schima	836036	836921	0.17	0.53	6	2																			Tree has grown on slope. Multiple elongated trunks recorded.
A0950	<i>Schima superba</i>	Schima	836042	836920	0.15	0.47	6	4																			Tree has grown on slope. Multiple elongated trunks recorded.
A0951	<i>Schima superba</i>	Schima	836043	836922	0.15	0.47	6	4																			Tree has grown on slope. Elongated trunk recorded.
A0952	<i>Schima superba</i>	Schima	836044	836922	0.25	0.79	8	4																			Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A0954	<i>Schima superba</i>	Schima	836044	836926	0.25	0.79	8	4																			Tree has grown on slope and twisted by climbers. Broken branches recorded.
A0957	<i>Schima superba</i>	Schima	836042	836924	0.3	0.94	11	7																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.
A0961	<i>Schima superba</i>	Schima	836037	836923	0.3	0.94	12	8																			Tree has grown on slope. Leaning trunk recorded.
A0962	<i>Schima superba</i>	Schima	836035	836923	0.17	0.53	8	3																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Leaning trunk recorded.
A0965	<i>Schima superba</i>	Schima	836026	836921	0.3	0.94	10	7																			Tree has grown on slope. Broken branches recorded.
A0966	<i>Schima superba</i>	Schima	836025	836922	0.3	0.94	10	4																			Tree has grown on slope and twisted by climbers. Multiple elongated trunks
A0967	<i>Schima superba</i>	Schima	836025	836921	0.25	0.79	8	6																			Tree has grown on slope. Elongated leaning trunk recorded.
A0969	<i>Schima superba</i>	Schima	836020	836921	0.15	0.47	7	3																			Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A1005	<i>Schima superba</i>	Schima	836062	836969	0.25	0.79	11	6																			Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A1006	<i>Schima superba</i>	Schima	836063	836968	0.14	0.44	7	3																			Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A1008	<i>Schima superba</i>	Schima	836061	836965	0.1	0.31	8	3																			Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A1009	<i>Schima superba</i>	Schima	836061	836963	0.15	0.47	6	3																			Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A1010	<i>Schima superba</i>	Schima	836060	836962	0.15	0.47	6	3																			Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A1011	<i>Schima superba</i>	Schima	836060	836961	0.17	0.53	7	4																			Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A1014	<i>Schima superba</i>	Schima	836061	836961	0.2	0.63	10	6																			Tree has grown on slope and twisted by climbers. Multiple trunks recorded.
A1019	<i>Schima superba</i>	Schima	836056	836943	0.17	0.53	10	5																			Tree has grown on slope and twisted by climbers. Broken trunk recorded.
A1020	<i>Schima superba</i>	Schima	836056	836941	0.15	0.47	8	3																			Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A1021	<i>Schima superba</i>	Schima	836055	836938	0.17	0.53	8	4																			Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A1024	<i>Schima superba</i>	Schima	836053	836935	0.2	0.63	9	6																			Tree has grown on slope and twisted by climbers. Multiple trunks and broken branches recorded.
A1026	<i>Schima superba</i>	Schima	836050	836932	0.3	0.94	12	10																			Tree has grown on slope and twisted by climbers.
A1027	<i>Schima superba</i>	Schima	836050	836929	0.3	0.94	13	10																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Multiple trunks recorded.
A1030	<i>Schima superba</i>	Schima	836055	836931	0.17	0.53	10	2																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Elongated trunk recorded.
A1031	<i>Schima superba</i>	Schima	836055	836933	0.15	0.47	10	2																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Elongated trunk recorded.
A1032	<i>Schima superba</i>	Schima	836055	836934	0.17	0.53	10	4																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Multiple elongated trunks recorded.
A1033	<i>Schima superba</i>	Schima	836055	836935	0.17	0.53	10	4																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Multiple elongated trunks recorded.
A1034	<i>Schima superba</i>	Schima	836058	836936	0.15	0.47	9	4																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Elongated trunk recorded.
A1035	<i>Schima superba</i>	Schima	836058	836937	0.17	0.53	10	4																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Elongated trunk recorded.
A1036	<i>Schima superba</i>	Schima	836059	836938	0.22	0.69	13	8																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Elongated trunk recorded.
A1037	<i>Schima superba</i>	Schima	836058	836939	0.22	0.69	11	8																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Elongated trunk recorded.
A1038	<i>Schima superba</i>	Schima	836059	836942	0.2	0.63	10	5																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Elongated trunk recorded.
A1039	<i>Schima superba</i>	Schima	836057	836943	0.2	0.63	10	2																			Tree has grown on slope. Elongated trunk recorded.
A1040	<i>Schima superba</i>	Schima	836061	836945	0.2	0.63	10	2																			Tree has grown on slope. Elongated trunk recorded.
A1042	<i>Schima superba</i>	Schima	836061	836949	0.17	0.53	13	8																			Tree has grown on slope and twisted by climbers. Tree growth has been obstructed by other plants in the vicinity. Multiple trunks recorded.
A1043	<i>Schima superba</i>	Schima	836059	836949	0.22	0.69	12	4																			Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Elongated trunk recorded.

A	B		C	D	E	F	G	H	I			J			K			L			M			N			O										
									Tree No.	Species Name	Common Name	Northing (m)	Easting (m)	Trunk Diameter (m)	Trunk Circumference (m)	Height (m)	Crown Spread (m)	Tree Form			Health Condition			Amenity Value				Survival Rate after Transplantation			Conflict with Development			Proposed Treatment			Brief comments and description
																		G	F	P	G	F	P	H	M	L		H	M	L	H	M	L	Partially - Soil Nailing	Yes - New Road Alignment/ Cut Slope	No	
A1044	<i>Schima superba</i>	Schima	836061	836950	0.23	0.72	12	6			1			1						1										Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Deformed trunk recorded.							
A1045	<i>Schima superba</i>	Schima	836061	836952	0.25	0.79	12	6			1			1						1										Tree has grown on slope and twisted by climbers. Elongated leaning trunk							
A1046	<i>Schima superba</i>	Schima	836062	836963	0.2	0.63	13	6			1			1						1										Tree has grown on slope and twisted by climbers. Elongated trunk recorded.							
A1096	<i>Schima superba</i>	Schima	836097	837015	0.17	0.53	10	3			1			1						1										Tree has been recorded on concrete slope. Elongated trunk has been recorded.							
A1132	<i>Schima superba</i>	Schima	836241	837075	0.15	0.47	6	2			1			1						1										Tree growth has been obstructed by plants in the vicinity.							
A1147	<i>Schima superba</i>	Schima	836264	837073	0.17	0.53	6	4			1			1																Elongated trunk has been recorded.							
A1149	<i>Schima superba</i>	Schima	836262	837078	0.2	0.63	10	4			1			1																Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Multiple trunk recorded.							
A1149	<i>Schima superba</i>	Schima	836262	837078	0.2	0.63	10	4			1			1																Tree has grown on slope and twisted by climbers. Tree growth has been obstructed by other plants in the vicinity.							
A1155	<i>Schima superba</i>	Schima	836265	837077	0.17	0.53	6	4			1			1																Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Multiple trunk recorded.							
A1156	<i>Schima superba</i>	Schima	836269	837077	0.3	0.94	12	7			1			1																Tree has grown on slope.							
A1157	<i>Schima superba</i>	Schima	836274	837078	0.17	0.53	10	6			1			1																Tree has grown on slope.							
A1158	<i>Schima superba</i>	Schima	836277	837079	0.17	0.53	10	6			1			1																Tree has grown on slope.							
A1159	<i>Schima superba</i>	Schima	836278	837078	0.17	0.53	8	4			1			1																Tree has grown on slope.							
A1161	<i>Schima superba</i>	Schima	836283	837079	0.3	0.94	13	8			1			1																Tree has grown on slope.							
A1162	<i>Schima superba</i>	Schima	836286	837079	0.3	0.94	12	6			1			1																Tree has grown on slope.							
A1178	<i>Schima superba</i>	Schima	836303	837078	0.25	0.79	10	8			1			1																Tree has grown on slope. Multiple trunks recorded.							
A1180	<i>Schima superba</i>	Schima	836304	837077	0.25	0.79	10	6			1			1																Tree has grown on slope. Broken branches recorded.							
A1189	<i>Schima superba</i>	Schima	836313	837069	0.25	0.79	10	5			1			1																Tree has grown on slope. Broken branches recorded.							
A1190	<i>Schima superba</i>	Schima	836313	837067	0.15	0.47	8	4			1			1																Tree has grown on slope. Multiple trunks recorded.							
A1191	<i>Schima superba</i>	Schima	836314	837066	0.17	0.53	10	7			1			1																Tree has grown on slope. Multiple trunks recorded.							
A1192	<i>Schima superba</i>	Schima	836315	837063	0.17	0.53	9	6			1			1																Tree has grown on slope. Multiple trunks recorded.							
A1193	<i>Schima superba</i>	Schima	836316	837061	0.15	0.47	7	3			1			1																Tree has grown on slope. Multiple trunks and broken branches recorded.							
A1194	<i>Schima superba</i>	Schima	836316	837059	0.17	0.53	8	6			1			1																Tree has grown on slope. Multiple trunks recorded.							
A1195	<i>Schima superba</i>	Schima	836315	837060	0.2	0.63	8	6			1			1																Tree has grown on slope. Multiple trunks recorded.							
A1200	<i>Schima superba</i>	Schima	836313	837064	0.17	0.53	9	2			1			1																Tree has grown on slope. Elongated trunk recorded.							
A1201	<i>Schima superba</i>	Schima	836312	837064	0.2	0.63	11	2			1			1																Tree has grown on slope. Elongated trunk recorded.							
A1238	<i>Schima superba</i>	Schima	836316	837055	0.17	0.53	7	5			1			1																Tree has grown on slope. Elongated broken branches recorded.							
A1239	<i>Schima superba</i>	Schima	836316	837052	0.2	0.63	8	6			1			1																Tree has grown on slope. Multiple trunks recorded.							
A1240	<i>Schima superba</i>	Schima	836316	837050	0.17	0.53	7	5			1			1																Tree has grown on slope.							
A1244	<i>Schima superba</i>	Schima	836326	837042	0.22	0.69	7	5			1			1																Tree has been twisted by climbers. Broken branches recorded.							
A1245	<i>Schima superba</i>	Schima	836329	837041	0.17	0.53	8	5			1			1																Tree has grown on slope. Elongated trunk recorded.							
A1246	<i>Schima superba</i>	Schima	836331	837041	0.15	0.47	6	4			1			1																Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Multiple trunks recorded.							
A1248	<i>Schima superba</i>	Schima	836331	837040	0.3	0.94	10	6			1			1																Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.							
A1249	<i>Schima superba</i>	Schima	836336	837038	0.15	0.47	6	2			1			1																Tree has grown on slope. Leaning trunk recorded.							
A1253	<i>Schima superba</i>	Schima	836345	837039	0.17	0.53	7	5			1			1																Tree has grown on slope. Multiple trunks recorded.							
A1254	<i>Schima superba</i>	Schima	836347	837040	0.17	0.53	6	3			1			1																Tree has grown on slope. Damaged trunk recorded.							
A1264	<i>Schima superba</i>	Schima	836340	837036	0.17	0.53	6	5			1			1																Tree has grown on slope. Multiple trunks recorded.							
A1265	<i>Schima superba</i>	Schima	836340	837036	0.17	0.53	8	3			1			1																Elongated trunk recorded.							
A1266	<i>Schima superba</i>	Schima	836335	837037	0.17	0.53	8	6			1			1																Tree has grown on slope.							
A1268	<i>Schima superba</i>	Schima	836327	837040	0.17	0.53	7	3			1			1																Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.							
A1269	<i>Schima superba</i>	Schima	836327	837038	0.15	0.47	6	3			1			1																Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.							
A1278	<i>Schima superba</i>	Schima	836314	837053	0.17	0.53	9	4			1			1																Tree has grown on slope and twisted by climbers. Tree growth has been obstructed by other plants in the vicinity. Multiple trunks recorded.							
A1302	<i>Schima superba</i>	Schima	836366	837044	0.2	0.63	10	8			1			1																Tree has grown on slope. Multiple trunks recorded.							
A1303	<i>Schima superba</i>	Schima	836368	837046	0.28	0.88	12	8			1			1																Tree has grown on slope. Multiple trunks recorded.							

A Tree No.	B		C Northing (m)	D Easting (m)	E Trunk Diameter (m)	F Trunk Circumference (m)	G Height (m)	H Crown Spread (m)	I			J			K			L			M			N			O Brief comments and description
	Species Name								Common Name	Tree Form	Health Condition			Amenity Value			Survival Rate after Transplantation			Conflict with Development			Proposed Treatment				
	G	F									P	G	F	P	H	M	L	H	M	L	Paritally - Soil Nailing	Yes - New Road Alignment/ Cut Slope	No	Fell	Retain	Transplant	
A1304	Schima superba	Schima	836371	837046	0.3	0.94	13	8			1	1			1			1	1								Tree has grown on slope. Multiple trunks recorded.
A1305	Schima superba	Schima	836371	837044	0.17	0.53	12	7			1	1			1			1	1								Tree has grown on slope. Multiple trunks recorded.
A1310	Schima superba	Schima	836387	837051	0.17	0.53	7	4			1	1			1			1	1								Tree has grown on slope. Elongated trunk recorded.
A1312	Schima superba	Schima	836389	837051	0.15	0.47	8	4			1	1			1			1	1								Tree has grown on slope. Elongated trunk recorded.
A1314	Schima superba	Schima	836390	837053	0.3	0.94	16	8			1	1			1			1	1								Tree has grown on slope. Multiple trunks recorded.
A1332	Schima superba	Schima(Burrt)	836364	837042	0.2	0.63	12	4			1	1			1			1	1								Tree has grown on slope. Multiple trunks recorded.
A1333	Schima superba	Schima	836364	837043	0.22	0.69	9	8			1	1			1			1	1								Tree has grown on slope. Dead branches recorded.
A1334	Schima superba	Schima	836364	837042	0.2	0.63	12	8			1	1			1			1	1								Tree has grown on slope and twisted by climbers. Multiple trunks recorded.
A1363	Schima superba	Schima	836410	837041	0.3	0.94	14	8			1	1			1			1	1								Tree has grown on slope and twisted by climbers.
A1366	Schima superba	Schima	836414	837042	0.25	0.79	15	6			1	1			1			1	1								Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Elongated trunk recorded.
A1367	Schima superba	Schima	836416	837043	0.3	0.94	13	8			1	1			1			1	1								Tree has grown on slope. Broken branches recorded.
A1373	Schima superba	Schima	836425	837044	0.22	0.69	10	5			1	1			1			1	1								Tree has grown on slope. Elongated trunk recorded.
A1374	Schima superba	Schima	836426	837044	0.2	0.63	12	6			1	1			1			1	1								Tree has grown on slope. Multiple dead trunks recorded.
A1375	Schima superba	Schima	836428	837043	0.25	0.79	10	6			1	1			1			1	1								Tree has grown on slope. Dead branches recorded.
A1376	Schima superba	Schima	836430	837042	0.4	1.26	14	8			1	1			1			1	1								Tree has grown on slope and twisted by climbers. Dead branches recorded.
A1377	Schima superba	Schima	836428	837041	0.2	0.63	8	3			1	1			1			1	1								Tree has grown on slope. Leaning Trunk and dead branches recorded.
A1380	Schima superba	Schima	836433	837041	0.15	0.47	8	2			1	1			1			1	1								Tree has grown on slope and twisted by climbers.
A1390	Schima superba	Schima	836426	837042	0.17	0.53	8	3			1	1			1			1	1								Tree growth has been obstructed by other plants. Elongated trunk recorded.
A1391	Schima superba	Schima	836424	837042	0.2	0.63	12	8			1	1			1			1	1								Tree has grown on slope. Multiple elongated trunks recorded.
A1392	Schima superba	Schima	836422	837042	0.17	0.53	12	5			1	1			1			1	1								Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A1393	Schima superba	Schima	836421	837041	0.2	0.63	13	8			1	1			1			1	1								Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A1394	Schima superba	Schima	836419	837041	0.22	0.69	15	8			1	1			1			1	1								Tree has grown on slope and twisted by climbers. Elongated trunk recorded.
A1397	Schima superba	Schima	836416	837040	0.2	0.63	12	3			1	1			1			1	1								Tree has grown on slope. Elongated trunk and broken branches recorded.
A1398	Schima superba	Schima	836415	837040	0.22	0.69	15	6			1	1			1			1	1								Tree has grown on slope. Elongated trunk recorded.
A1399	Schima superba	Schima	836415	837040	0.15	0.47	9	4			1	1			1			1	1								Tree has grown on slope. Leaning elongated trunk recorded.
A1402	Schima superba	Schima	836409	837041	0.17	0.53	8	3			1	1			1			1	1								Tree has grown on slope. Elongated trunk recorded.
A1404	Schima superba	Schima	836405	837043	0.4	1.26	16	13			1	1			1			1	1								Tree has grown on slope. Multiple trunks recorded.
A1412	Schima superba	Schima	836399	837049	0.23	0.72	6	5			1	1			1			1	1								Tree has grown on slope and twisted by climbers. Leaning trunk recorded.
A1432	Schima superba	Schima	836452	837026	0.23	0.72	12	5			1	1			1			1	1								Tree has grown on slope and twisted by climbers.
A1434	Schima superba	Schima	836453	837024	0.23	0.72	9	3			1	1			1			1	1								Tree has grown on slope and twisted by climbers. Tree growth has been obstructed by other plants in the vicinity.
A1435	Schima superba	Schima	836455	837023	0.17	0.53	6	2			1	1			1			1	1								Tree has grown on slope. Broken leaning trunks recorded
A1440	Schima superba	Schima	836463	837015	0.2	0.63	8	5			1	1			1			1	1								Tree has grown on slope and twisted by climbers.
A1443	Schima superba	Schima	836453	837023	0.15	0.47	3	0.7			1	1	1		1			1	1								Tree has grown on slope and twisted by climbers. Broken branches recorded.
A1457	Schima superba	Schima	836476	837004	0.13	0.41	6	3			1	1			1			1	1								Tree has grown on slope. Broken branches recorded.
A1458	Schima superba	Schima	836477	837003	0.2	0.63	8	3			1	1			1			1	1								Tree has grown on slope. Multiple trunks recorded.
A1461	Schima superba	Schima	836470	837001	0.17	0.53	5	5			1	1			1			1	1								Tree has grown on slope. Leaning trunk recorded.
A1464	Schima superba	Schima	836491	837006	0.5	1.57	14	10			1	1			1			1	1								Tree has grown on slope and twisted by climbers. Broken branches recorded.
A1466	Schima superba	Schima	836500	837006	0.2	0.63	6	4			1	1			1			1	1								Tree has grown on slope and twisted by climbers. Tree growth has been obstructed by other plants in the vicinity.
A1473	Schima superba	Schima	836489	837003	0.2	0.63	6	6			1	1			1			1	1								Tree has grown on slope. Elongated trunk recorded.
A1477	Schima superba	Schima	836498	837004	0.17	0.53	7	4			1	1	1		1			1	1								Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.
A1487	Schima superba	Schima	836539	837001	0.3	0.94	14	8			1	1			1			1	1								Tree has grown on slope and twisted by climbers. Multiple trunks recorded.
A1488	Schima superba	Schima	836542	837002	0.3	0.94	12	7			1	1			1			1	1								Tree has grown on slope and twisted by climbers. Broken branches recorded.
A1489	Schima superba	Schima	836542	837004	0.25	0.79	13	8			1	1			1			1	1								Tree has grown on slope. Broken branches recorded.
A1490	Schima superba	Schima	836545	837004	0.3	0.94	13	8			1	1			1			1	1								Tree has grown on slope. Multiple trunks recorded.
A1492	Schima superba	Schima	836547	837005	0.25	0.79	10	7			1	1			1			1	1								Tree has been twisted by climbers.
A1496	Schima superba	Schima	836557	837007	0.13	0.41	6	5			1	1	1		1			1	1								Tree has been twisted by climbers and nearly dead.
A1497	Schima superba	Schima	836561	837010	0.2	0.63	7	6			1	1	1		1			1	1								Tree has been twisted by climbers and nearly dead. Deformed trunk recorded.
A1499	Schima superba	Schima	836561	837009	0.15	0.47	6	3			1	1			1			1	1								Tree has been twisted by climbers. Deformed trunk recorded.
A1500	Schima superba	Schima	836529	837003	0.2	0.63	6	4			1	1			1			1	1								Tree has grown on slope and twisted by climbers.

A Tree No.	B Species Name Common Name		C Northing (m)	D Easting (m)	E Trunk Diameter (m)	F Trunk Circumference (m)	G Height (m)	H Crown Spread (m)	I Tree Form			J Health Condition			K Amenity Value			L Survival Rate after Transplantation			M Conflict with Development			N Proposed Treatment			O Brief comments and description
	G	F	P	G	F	P	H	M	L	H	M	L	Paritally - Soil Nailing	Yes - New Road Alignment/ Cut Slope	No	Fell	Retain	Transplant									
A1503	<i>Schima superba</i>	Schima	836559	837020	0.17	0.53	6	3				1	1														Tree has grown on slope.
A1515	<i>Schima superba</i>	Schima	836533	836999	0.2	0.63	8	3				1		1													Tree grown on slope and twisted by climbers. Tree growth has been obstructed by other plants in the vicinity.
A1517	<i>Schima superba</i>	Schima	836529	837003	0.16	0.50	6	4				1	1														Tree has grown on slope. Multiple damaged trunks recorded.
A1520	<i>Schima superba</i>	Schima	836521	837002	0.17	0.53	8	6				1	1														Tree has grown on slope. Multiple damaged trunks recorded.
A1540	<i>Schima superba</i>	Schima	836570	837024	0.17	0.53	7	3				1		1	1												Tree has grown on slope. Elongated trunk recorded.
A1541	<i>Schima superba</i>	Schima	836569	837025	0.17	0.53	6	3				1		1													Tree has grown on slope.
A1553	<i>Schima superba</i>	Schima	836559	837006	0.25	0.79	8	4				1		1													Tree has been twisted by climbers and found nearly dead.
A1574	<i>Schima superba</i>	Schima	836579	837015	0.13	0.41	8	3				1	1	1													Elongated trunk recorded.
A1576	<i>Schima superba</i>	Schima	836583	837014	0.15	0.47	8	4				1		1													Multiple elongated trunk recorded.
A1591	<i>Schima superba</i>	Schima	836609	837004	0.22	0.69	10	8				1	1	1													Multiple elongated trunks recorded.
A1595	<i>Schima superba</i>	Schima	836613	837002	0.22	0.69	9	7				1	1	1													Elongated trunk recorded.
A1596	<i>Schima superba</i>	Schima	836612	837002	0.25	0.79	13	8				1	1	1													Elongated trunk recorded.
A1608	<i>Schima superba</i>	Schima	836626	836990	0.2	0.63	7	6				1		1													Multiple broken trunks recorded.
A1609	<i>Schima superba</i>	Schima	836628	836988	0.22	0.69	10	6				1		1													Tree has been twisted by climbers. Tree growth has been obstructed by other plants in the vicinity.
A1610	<i>Schima superba</i>	Schima	836630	836986	0.3	0.94	12	8				1		1													Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.
A1612	<i>Schima superba</i>	Schima	836632	836983	0.25	0.79	9	7				1	1	1													Elongated and broken trunk recorded.
A1613	<i>Schima superba</i>	Schima	836636	836981	0.22	0.69	7	6				1		1													Tree growth has been obstructed by other plants in the vicinity. Elongated trunk recorded.
A1615	<i>Schima superba</i>	Schima	836649	836970	0.2	0.63	12	6				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1616	<i>Schima superba</i>	Schima	836648	836969	0.2	0.63	10	5				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1619	<i>Schima superba</i>	Schima	836647	836968	0.17	0.53	12	7				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1626	<i>Schima superba</i>	Schima	836638	836974	0.17	0.53	7	8				1	1	1													Tree has grown on slope. Multiple trunks recorded.
A1641	<i>Schima superba</i>	Schima	836623	836988	0.25	0.79	8	4				1	1	1													Tree has grown on slope. Multiple trunks recorded.
A1642	<i>Schima superba</i>	Schima	836619	836991	0.3	0.94	8	8				1		1													Tree has been twisted by climbers and found nearly dead.
A1644	<i>Schima superba</i>	Schima	836627	836987	0.15	0.47	6	3				1	1	1													Multiple trunks recorded.
A1647	<i>Schima superba</i>	Schima	836651	836969	0.1	0.31	8	2				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1648	<i>Schima superba</i>	Schima	836653	836969	0.2	0.63	10	5				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1649	<i>Schima superba</i>	Schima	836652	836968	0.1	0.31	7	1.5				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1650	<i>Schima superba</i>	Schima	836655	836968	0.15	0.47	7	3				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1651	<i>Schima superba</i>	Schima	836655	836967	0.1	0.31	6	1.5				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1652	<i>Schima superba</i>	Schima	836654	836966	0.15	0.47	8	2				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1654	<i>Schima superba</i>	Schima	836651	836968	0.2	0.63	8	1.5				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1655	<i>Schima superba</i>	Schima	836656	836969	0.15	0.47	7	1.5				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1656	<i>Schima superba</i>	Schima	836657	836969	0.22	0.69	8	5				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1657	<i>Schima superba</i>	Schima	836658	836968	0.3	0.94	9	6				1	1	1													Tree growth has been obstructed by other plants in the vicinity. Elongated trunk recorded.
A1658	<i>Schima superba</i>	Schima	836657	836965	0.2	0.63	10	6				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1666	<i>Schima superba</i>	Schima	836661	836962	0.5	1.57	13	10				1	1	1													Tree has grown on slope. Tree has been mature in size.
A1667	<i>Schima superba</i>	Schima	836659	836958	0.25	0.79	9	4				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1670	<i>Schima superba</i>	Schima	836662	836957	0.1	0.31	5	2				1		1													Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity. Elongated trunk recorded.
A1676	<i>Schima superba</i>	Schima	836673	836951	0.1	0.31	6	1.5				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1679	<i>Schima superba</i>	Schima	836672	836952	0.15	0.47	7	4				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1682	<i>Schima superba</i>	Schima	836671	836952	0.21	0.66	9	5				1	1	1													Tree has grown on slope.
A1685	<i>Schima superba</i>	Schima	836667	836953	0.1	0.31	5	2				1	1	1													Tree has grown on slope. Tree growth has been obstructed by other plants in the vicinity.
A1690	<i>Schima superba</i>	Schima	836661	836966	0.17	0.53	8	3				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1691	<i>Schima superba</i>	Schima	836684	836953	0.2	0.63	9	5				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1692	<i>Schima superba</i>	Schima	836682	836952	0.35	1.10	10	5				1	1	1													Tree has grown on slope. Elongated trunk recorded.
A1693	<i>Schima superba</i>	Schima	836680	836952	0.2	0.63	8	3				1	1	1													Tree has grown on slope. Elongated trunk recorded.

A	B		C	D	E	F	G	H	I			J			K			L			M			N			O	
	Tree No.	Species Name	Common Name	Northing (m)	Easting (m)	Trunk Diameter (m)	Trunk Circumference (m)	Height (m)	Crown Spread (m)	Tree Form			Health Condition			Amenity Value			Survival Rate after Transplantation			Conflict with Development			Proposed Treatment			Brief comments and description
										G	F	P	G	F	P	H	M	L	H	M	L	H	M	L	Partially - Soil Nailing	Yes - New Road Alignment/ Cut Slope	No	
A2031	<i>Schima superba</i>	Schima	836167	837034	0.18	0.57	7	5			1		1															Elongated trunk has been recorded. Tree has been recorded on concrete slope.
A2032	<i>Schima superba</i>	Schima	836170	837038	0.22	0.69	12	7			1		1															Elongated trunk has been recorded. Tree has been recorded on concrete slope.
A2033	<i>Schima superba</i>	Schima	836171	837039	0.21	0.66	12	6			1		1															Two main trunks have been recorded. Tree has been recorded on concrete
A2035	<i>Schima superba</i>	Schima	836175	837037	0.13	0.41	6	5			1		1															Elongated trunk has been recorded. Tree has been recorded on concrete slope.
A2037	<i>Schima superba</i>	Schima	836173	837036	0.15	0.47	10	5			1		1															Elongated trunk has been recorded. Tree has been recorded on concrete slope.
A2038	<i>Schima superba</i>	Schima	836179	837038	0.21	0.66	11	6			1		1															Elongated trunk has been recorded. Tree has been recorded on concrete slope.
A2039	<i>Schima superba</i>	Schima	836181	837039	0.24	0.75	9	6			1		1															Elongated trunk has been recorded. Tree has been recorded on concrete slope.
A0120	<i>Scolopia chinensis</i>	Chinese Scolopia	835612	836796	0.2	0.63	6	3			1		1															Tree has grown on slope. Broken branches recorded.
A0716	<i>Syzygium hancei</i>	Hance's Syzygium	835796	836903	0.2	0.63	10	7			1		1															Tree has grown on slope. Multiple trunks recorded.
A1121	<i>Syzygium levinei</i>	Hance's Syzygium	836186	837042	0.13	0.41	6	4			1		1															Tree has been twisted by climbers and recorded on concrete slope. Tree growth has been obstructed by plants in the vicinity.
A1315	<i>Syzygium levinei</i>	Levine's Syzygium	836398	837052	0.3	0.94	13	8			1		1															Tree has grown on slope. Elongated trunk recorded.
A0014	<i>Terminalia catappa</i>	Indian Almond	835564	836628	0.3	0.94	5	2			1		1															Trees roots have been covered by concrete platform. Leaning trunk and broken branches recorded.
A0015	<i>Viburnum odoratissimum</i>	Sweet Viburnum	835561	836646	0.5	1.57	10	6			1		1															Tree growth has been obstructed by other plants in the vicinity. Broken branches recorded.
A1002	<i>Viburnum odoratissimum</i>	Sweet Viburnum	836054	836979	0.2	0.63	6	4			1		1															Tree has grown on slope and twisted by climbers. Tree growth has been obstructed by other plants in the vicinity. Multiple trunks and broken branches