



## **Appendix 11.3**


### **Seabed Features Chart**





Legend :

- Survey boundary
- Extend coverage
- Disturbed seabed
- Disused fuel dolphin
- Possible dumped materials
- Seafloor with numerous debris
- ▲ SC001 1.5x1.5x2 Debris  
Sonar contact (length x width x height in metres)
- ▲ MC001 11x4.5x1 Ferry vessel  
Magnetic contact
- ▲ SD001 Possible dumped pipe  
Seismic contact
- Anchor scar
- As found pipeline
- Depression



Project :

**WORKS ORDER NO. GE/2010/02.50**  
**AGREEMENT NO. CE/43/2010(HY)**  
**CENTRAL KOWLOON ROUTE - DESIGN AND CONSTRUCTION**  
**MARINE GROUND INVESTIGATION AND GEOPHYSICAL SURVEYS**

FIGURE NUMBER : 3


**SEA BED FEATURES**

Notes :


1. Survey Date : 30/01/2012
2. Survey Grid : Hong Kong Principal Grid
3. Survey Datum : Hong Kong Principal Datum
4. Positioning : C-Nav GcGps (Globally corrected GPS)
5. Equipment : Odom Echotrac Mk III Echo Sounder  
LVS Boomer System  
272TD Side Scan Sonar System with Digital Tow Fish
6. Coastline taken from 1:1,000 Survey Sheets, Survey and Mapping Office, Lands Department

Revision No.	Date	Drawn by	Checked by	Approved by	Remarks
0	09/02/2012	Chester Quek	W L Lam	Margie Chen	Preliminary

METRIC SCALE 1:500




Client :



**Civil Engineering and Development Department**

Surveyor :



**EGS (ASIA) LIMITED**  
11/F, 250-252, SHEWAN ROAD, HONG KONG

Job No. : HK225312