


**EXISTING CONDITION** 



DAY 1 WITHOUT MITIGATION MEASURES







AGREEMENT NO. CE 42/2008 (CE)
TSEUNG KWAN 0 - LAM TIN TUNNEL AND ASSOCIATED WORKS - INVESTIGATION
PHOTOMONTAGE FROM VSR TKO / R1 (SHEET 1 OF 2)

SCALE	N. T. S.	DATE	FEB 2013	
CHECK	TO	DRAWN	LW	
JOB No.	Yora	FIGURE No.		REV
	MCA75	10.8.5.2		