

EXISTING CONDITION



DAY 1 WITHOUT MITIGATION MEASURES







AGREEMENT NO. CE 42/2008 (CE)
TSEUNG KWAN O - LAM TIN TUNNEL AND ASSOCIATED WORKS - INVESTIGATION

PHOTOMONTAGE FROM VSR LT / R5 (SHEET 1 OF 2)

SCALE	N. T. S.	DATE	FEB 2013	
CHECK	TO	DRAWN	LW	
JOB No.		FIGURE No.		REV
	MCA75	10.8.7.6		