



LR1 Major Transport Route



LR3.1 Engineered Slope along with Semi-natural Dense Hillside Vegetation



LR5.1 Natural Stream at the east boundary of the ARQ




LR2 Hillside Woodland




LR4 Hillside Grassland / Shrubland



LR6 Urban Development Area



LR3 Semi-natural Dense Hillside Vegetation



LR5 Natural Stream



LR7 Rural Development Area

A	FIRST ISSUE	TST	03/12
Rev	Description	By	Date

Consultant
ARUP

Contract No. and Title
 Agreement No. CE 18/2012(CE)
 Anderson Road Quarry - Investigation

Drawing title
 PHOTO OF LANDSCAPE RESOURCES
 (Sheet 1 of 3)

Drawing no. 227724/L/2210		Rev. -	
Drawn CN	Date 03/13	Checked CL	Approved SYC
Scale N. T. S.		Status PRELIMINARY	