


ENVIRONMENTAL MONITORING AND AUDIT MANUAL FOR
 DECOMMISSIONING OF WEST PORTION OF THE MIDDLE ASH LAGOON AT TSANG TSUI, TUEN MUN

FIGURE 5.1 - PROPOSED WATER QUALITY MONITORING STATIONS

FIGURE	REVISION	
5.1	2	
SCALE	DATE	
AS SHOWN	06/2014	