


- LEGEND**
- • • • • 250m CONSULTATION ZONE OF WENT LANDFILL EXTENSION
 - |— BOUNDARY OF WENT LANDFILL EXTENSION
 - — — — — INTEGRATED WASTE MANAGEMENT FACILITIES
 - - - - - SLUDGE TREATMENT FACILITY
 - BOUNDARY OF EXISTING WENT LANDFILL
 - [Blue hatched box] LOW ZONE
 - [Yellow cross-hatched box] SUBJECT SITE PFA PLATFORM (DECOMMISSIONING AREA)
 - [Hexagonal pattern box] CONSTRUCTION ACCESS ROAD (SOUTH) UPGRADING OF EXISTING PAVED ACCESS ROAD
 - [Horizontal line pattern box] CONSTRUCTION ACCESS ROAD (SOUTH) DECOMMISSIONING AREA
 - [Diagonal line pattern box] CONSTRUCTION ACCESS ROAD (NORTH) (DECOMMISSIONING AREA)
 - [Dotted pattern box] FENCE OFF AREA (NO DECOMMISSIONING)

ENVIRONMENTAL IMPACT ASSESSMENT FOR
DECOMMISSIONING OF WEST PORTION OF THE MIDDLE ASH LAGOON AT TSANG TSUI, TUEN MUN

FIGURE 10.1 - CONSULTATION ZONE OF THE PROPOSED WENT LANDFILL EXTENSIONS

FIGURE	REVISION	
10.1	2	
SCALE	DATE	
AS SHOWN	06/2014	