


Survey Date:	18/03/2014		1	Map No:	MWC	01
BH Item No.	MWC01	Declared Monument	Ye	es	4	lo
Name of BH	Tung Chung Battery	AMO Announced	4	2	3	No- Grade
Village/Town/ Location	Rocky Lion Hill, Ma Wan Chung	Grading	Propose	d Monum	ent	
District	Tung Chung, Lantau Island	Gov. Historic Sites	Yes No			
Building Type	Battery	Land	Leaseholder Current Us			
Date of Construction	Completed in 1817	Condition	Gover	nment	Pu	blic
Present Use	Preserved Heritage	Current Condition	In U	Jse	Aban	doned
Elements	Building Materials		Building	Methods	•	
Wall	Granite Blocks	Built	by Laying	Granite E	Blocks	
Additional Building Description (Optional)	Remains of Tung Chung Battery include a likely utilized as a gun emplacement.	an L-shaped wall	all and corner platform which was mos			
Historical /Cultural Information (Optional)	monuments). It is located on a prominent of the battery were rediscovered in 1980 to Battery was completed in 1817 with the put threatened the coasts and seas of souther in the Guangdong Annals, which recounted Lion Hill" — the literal translation of Shek States	peneath thick folia urpose of protecting on China. The consection and how two forts of the.	ge. Const ng Tung C struction o	ruction or hung Bay of the batt	the Tung from pira ery was r	g Chung ates that ecorded
Façade Other View(s) / Detail(s) (Optional):	Representative					
(Optional): Recorded by Kat	thy Chan Date 18/03/2014	Checked by Ant	thony Siu	Date	18/03/20	14



Map No: Survey Date: 18/03/2014 MWC02 **Declared** BH Item No. MWC02 Yes No Monument No Name of BH Broken Bridge 4 2 3 **AMO** Grade **Announced** Village/Town/ Grading Ma Wan Chung **Proposed Monument** Location Gov. Historic **District** Yes Tung Chung, Lantau Island No **Sites Building Type** Leaseholder **Current User** Bridge Land Date Condition Not Known Private No Construction Current **Present Use** Abandoned In Use Abandoned Condition **Elements Building Materials Building Methods Bridge Frame** Concrete Molded Bridge Deck Timber plank Laying Additional **Building** It is an old footbridge connecting the jetty. The bridge existed before 1970s as it can be seen on **Description** aerial photo taken in 1973. (Optional) Historical /Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional): Recorded by Kathy Chan Date 18/03/2014 Date 18/03/2014 Checked by Anthony Siu



Survey Date:	18/03/2	014			Map No:	MWC	03	
BH Item No.	MWC03		Declared Monument	¥	9S	١	lo	
Name of BH	Earth Shr	ine	AMO Announced	4	2	3	No Grade	
Village/Town/ Location	Ma Wan (Chung	Grading	Propose	d Monum	ent		
District	Tung Chu	ng, Lantau Island	Gov. Historic Sites	¥	9S	١	lo	
Building Type	Earth Shr	ine	- Land	Leaseholder Current User				
Date of Construction	Not Know	n	Condition	Priv	/ate	Local \	/illagers	
Present Use	Earth Shr	ine	Current Condition	In l	Jse	Aban	doned	
Elements		Building Materials		Building	Methods	5		
Shrine Chamber		Concrete	Built into a Ch		th ridged f ised platfo		Doors	
Earth God		Ceramic		Placed	on Altar			
Altar		Timber	Timber Tabl	e Placed	inside Shr	ine Cham	nber	
Additional Building Description (Optional) Historical	The shrine	The shrine is built on a prototype of a local temple.						
/Cultural Information (Optional)								
		Representative	Photo(s)					
Façade								
Other View(s) / Detail(s) (Optional):				TAME OF THE PROPERTY OF THE PR	A A A A A A A A A A A A A A A A A A A			
Recorded by Ka	thy Chan	Date 18/03/2014	Checked by Ant	thony Siu	Date	18/03/20	14	



Survey Date: 18/03/2014 Map No: STT01 Declared BH Item No. STT01 Yes No Monument No-Name of BH Hau Wong Temple, Tung Chung 1 2 3 **AMO** Grade **Announced** Village/Town Grading Sha Tsui Tau **Proposed Monument** Name Gov. Historic District Tung Chung, Lantau Island Yes Nο Sites **Building Type** Leaseholder Temple **Current User** Land Date of Condition was Built at least by 1765 CTC* Local Villagers Construction Current **Present Use** Temple In Use **Abandoned** Condition **Elements Building Materials Building Methods** Glazed Roof Tile with Shiwan Ceramic concave, Cylindrical Tile Combined - Liuli Glazed Roof Tile Decoration on the Main Ridge Tiles Tile End Liuli Glazed Tiles with Drippers Dragon Fish Ends + Shiwan Ceramic Ridge Type Decoration include Dragon Fish with N/A Phoenix ends" Wall Granite Foundation + Grey Bricks Painted Brick Line Recessed Entrance + Rectangular Opening Type + Timber + Granite Door Flush Door+ Rectangular Block Door Drum Hau Wong temple is a grade 2 historic building and lies within the Sha Tsui Tau Site of Additional Archaeological Interest, within 100m of Tung Chung bay and the outlet of the Tung Chung River. Building It is a two halls-three bays structure with a Forecourt. The temple has been renovated several Description times since its establishment. Two tablets built in interior walls record two times of renovation and (Optional) the names of the donors. An inscription of a bronze bell within the temple suggests that the temple was built at least by Historical 1765 and is the largest Hau Wong temple on Lantau island. The temple is used to worship of /Cultural Yuen Liangjie and a ceremony is held on the forecourt on the 18th of the eighth month in the Information Lunar calendar every year with activities such as Chinese operas and gatherings in the open area (Optional) of the temple, to celebrate the birthday of Hau Wong. Representative Photo(s) Façade



Other View(s) / Detail(s) (Optional):

Tablets in Hau Wong Temple (Tung Chung)




Bell in Hau Wong Temple (Tung Chung), Qing Dynasity

Recorded by Kathy Chan


Date 18/03/2014

Checked by Anthony Siu


Date 18/03/2014




Survey Date: 18/03/2014 Map No: STT02 **Declared** BH Item No. STT02 Yes No Monument No Name of BH Earth Shrine 4 2 3 **AMO** Grade Announced Village/Town Grading Sha Tsui Tau **Proposed Monument** Name Gov. Historic **District** Tung Chung, Lantau Island Yes No Sites Leaseholder **Current User Building Type** Shrine Land Date of Condition Not Known Private Local Villagers Construction Current **Present Use** Shrine In Use **Abandoned** Condition **Elements Building Materials Building Methods** Door Shape Concrete Molded and Elected on Altar Frame Earth Gods Stone Placed on Altar Door Gods Paper + Concrete Paper glued to Concrete Tablets **Additional Building Description** (Optional) Historical /Cultural It is a earth shrine built near water. Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional): Recorded by Kathy Chan Date 18/03/2014 Checked by Anthony Siu Date 18/03/2014




Survey Date:	18/03/2	014	_	ſ	Map No:	STT0	3
BH Item No.	STT03		Declared Monument	¥	es	N	lo .
Name of BH	Shrine		AMO Announced	4	2	3	No Grade
Village/Town Name	Sha Tsui	Гаu	Grading	ent	ent		
District	Tung Chu	ng, Lantau Island	Gov. Historic Sites	Yes No			
Building Type	Shrine		Land	Leaseholder Current U			
Date of Construction	Not Know	n	Condition	Priv	/ate	Local V	/illagers
Present Use	Shrine		Current Condition	In U	Jse	Aban	doned
Elements		Building Materials		Building	Methods	3	
Altar		Concrete	Bu	ilt into Ste	pped Plat	tfom	
Gods		Ceramic		Placed	on Altar		
Roof		Metal + Timber	Wooden Bro	oad Place	d on Meta	al Framev	vork
Additional Building Description (Optional) Historical	It is built r	next to STT02 Earth Shrine.					
/Cultural Information (Optional)	It is a shri	ne which serves various gods.					
	1	Representative	Photo(s)	1 21			
Façade							
Other View(s) / Detail(s) (Optional):							
Recorded by Ka	thy Chan	Date 18/03/2014	Checked by An	thony Siu	Date	18/03/20	14




Survey Date: 18/03/2014 Map No: NA01 **Declared** BH Item No. NA01 Yes No **Monument** No Name of BH Earth Shrine 4 2 3 **AMO** Grade Announced Village/Town Grading Ngau Au **Proposed Monument** Name Gov. Historic **District** Tung Chung, Lantau Island Yes No Sites **Shrine Type** Open Altar with a Stone Leaseholder **Current User** Land Date of Condition Not Known Private Local Villagers Construction Current **Present Use** Shrine In Use **Abandoned** Condition **Elements Building Materials Building Methods** Altar Pebbles + Concrete Concrete Paved on Top of Pebbles Earth God Stone Decorated with Ribbon Laying on Top of Altar Additional **Building Description** (Optional) Historical /Cultural The earth shrine is built near a footbridge and a stream to the northeast of Ngau Au village. It might be worshiped as Qiaotougong (橋頭公) or Shuitougong (水頭公). Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional): Recorded by Kathy Chan Date 18/03/2014 Date 18/03/2014 Checked by Anthony Siu




Name of BH Earth Shrine Earth	Survey Date:	18/03/2	014	_	ſ	Map No:	: NAC)2	
Name of BH Earth Shrine at Entrance Gate Announce Announce Carading Proposed Monument	BH Item No.	NA02			¥	'es	١	No	
Ngau Au	Name of BH	Earth Shri	ine at Entrance Gate	_	4	2	3		
Building Type Earth Shrine Land Condition Private Local Villagers Present Use Earth Shrine Current Condition In Use Abandoned Elements Building Materials Building Metrials Building Metrials In Use Placet Platform Earth God Stone Placed on Top Of A Concrete Platform Door Gods Painting on Paper Glued to the Sidewalls of the Alter Additional Building		Ngau Au			Propose	ed Monu	ment		
Date of Construction Not Known Condition Private Local Villagers	District	Tung Chu	ng, Lantau Island	Historic	¥	'es	١	Ю	
Construction Not Known Current Condition In Use Abandoned	Building Type	Earth Shr	ine	Land	Lease	holder	Curre	nt User	
Elements Building Materials Building Materials Building Methods Altar Concrete Built In Arm-Chair Form Bounding Entrance Wall Earth God Stone Placed on Top Of A Concrete Platform Door Gods Painting on Paper Glued to the Main Altar Wall Couplet Written on Paper Glued to the Sidewalls of the Alter Additional Building Description (Optional) Historical / Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional): Other View(s) / Detail(s) (Optional):		Not Know	n		Pri	vate	Local \	/illagers	
Altar Concrete Built In Arm-Chair Form Bounding Entrance Wall Earth God Stone Placed on Top Of A Concrete Platform Door Gods Painting on Paper Glued to the Main Altar Wall Couplet Written on Paper Glued to the Sidewalls of the Alter Additional Building Description (Optional) Historical / Cultural Information (Optional) Façade Other View(s) / Detail(s) (Optional):	Present Use	Earth Shr	ine		In Use Abandone				
Earth God Stone Placed on Top Of A Concrete Platform Door Gods Painting on Paper Glued to the Main Altar Wall Couplet Written on Paper Glued to the Sidewalls of the Alter Additional Building Description (Optional) Historical / Cultural Information (Optional) Façade Other View(s) / Detail(s) (Optional): To earth shrine is built facing away from the village. The entrance wall is used as the back of the shrine. Door gods (門神) are also worshiped in this shrine. Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Elements		Building Materials		Buildi	ing Meth	nods		
Door Gods Painting on Paper Glued to the Main Altar Wall Couplet Written on Paper Glued to the Sidewalls of the Alter Additional Building Description (Optional) Historical //Cultural Information (Optional) Façade Other View(s) / Detail(s) (Optional): Other View(s) / Detail(s) (Optional):	Altar		Concrete	Built In Arm	-Chair Fo	rm Boun	nding Entrar	nce Wall	
Couplet Written on Paper Glued to the Sidewalls of the Alter Additional Building Description (Optional) Historical / Cultural Information (Optional) Façade Other View(s) / Detail(s) (Optional):	Earth God		Stone	Placed	on Top (Of A Con	crete Platfo	orm	
Additional Building Description (Optional) Historical /Cultural Information (Optional) Façade Other View(s) / Detail(s) (Optional):	Door Gods		Painting on Paper	G	lued to th	ne Main A	Altar Wall		
Building Description (Optional) Historical (Cultural Information (Optional) Façade Other View(s) / Detail(s) (Optional):	Couplet		Written on Paper	Glue	d to the	Sidewalls	s of the Alte	r	
Façade Other View(s) / Detail(s) (Optional):	Building Description (Optional) Historical /Cultural Information			d in this shrine.	ntrance v	vall is us	ed as the b	ack of the	
	Façade Other View(s) / Detail(s)								
		athy Chan	Date 18/03/2014	Checked by	Anthony	Siu D	ate 18/03/2	2014	




Survey Date:	18/03/2	014			1	Map No:	NAC)3
BH Item No.	NA03			Declared Monument	¥	es	1	No
Name of BH	Entrance	Gate of Ngau Au		AMO Announced	4	2	3	No Grade
Village/Town Name	Ngau Au			Grading	Propose	ed Monur	ment	
District	Tung Chu	ng, Lantau Island		Gov. Historic Sites	¥	'es	1	No
Building Type	Entrance	Gate		Land	Lease	holder	Curre	nt User
Date of Construction	Not Know	n		Condition	Pri	vate	Local \	/illagers
Present Use	Entrance	Gate		Current Condition	In l	Use	Aban	doned
Elements		Building Materials			Buildi	ing Meth	ods	
Gate	S	itone + Concrete + Brick		Concre	ete Finish	ing on St	tone Struct	ure
Wall		Stone			Built	with Stor	nes	
Door Gods		Painted on Paper		Glu				
Additional Building Description (Optional)		nce gate was once renovat ce, possibly made of timbe ing away.						
Historical /Cultural Information (Optional)								
	T	Represen	tative F	Photo(s)		4.00		
Façade								
Other View(s) / Detail(s) (Optional): Back View of the Entrance Gate						Ante		
Recorded by Ka	thy Chan	Date 18/03/2014		Checked by	Anthony	Siu D a	ate 18/03/2	2014




Survey Date:	18/03/2014	1			Map No:	THC)1
BH Item No.	TH01		Declared Monument	¥	es	1	No
Name of BH	Ruined Villag	ge Houses near No. 4	AMO Announced	4	2	3	No Grade
Village/Town Name	Tung Hing		Grading	Propose	ed Monu	ment	
District	Tung Chung,	Lantau Island	Gov. Historic Sites	¥	' es	1	No
Building Type	Residential h	ouse	Land	Lease	holder	Curre	nt User
Date of Construction	Late 19th Cer	ntury to Early 20 th Century	Condition	Private No			
Present Use	Vacant		Current Condition	In l	Use	Aban	doned
Elements	В	uilding Materials		Buildi	ng Meth	ods	
Roof Tile	Grey Cylind	rical Tile + Red Concave Tile	e Conc	ave, Cylir	ndrical Ti	le Combine	ed
Tile End	G	rey Cylindrical Tile		Witho	out Dripp	ers	
Wall	Granite Fou	undation + Grey Brick + Red Brick + Mortar				ners Bond I vith Mortar	Method
Door	Timbe	r + Granite Door Drum	Rectangula Re			ype + Flush Door Drum	Door +
Additional Building Description (Optional)		joint village houses with couron is of triangular shape.					
Historical /Cultural Information (Optional)							
		Representativ	re Photo(s)		4		
Façade Other View(s) /							
Detail(s) (Optional):							
Recorded by Ka	thy Chan Da	ate 18/03/2014	Checked by	Anthony	Siu D	ate 18/03/2	2014




Survey Date:	18/03/2	014		١	Map No:	THO)2	
BH Item No.	TH02		Declared Monument	¥	es	1	No	
Name of BH	Entrance Hing	Gate with Village Wall at Tune	AMO Announced	1	2	3	No Grade	
Village/Town Name	Tung Hing	3	Grading	Propose	ed Monur	ment		
District	Tung Chu	ing, Lantau Island	Gov. Historic Sites	¥	'es	1	No	
Building Type	Entrance	Gate With Village Wall	Land	Leaseholder Current Use				
Date of Construction	Not Know	'n	Condition	Private Local Villag				
Present Use	Entrance	Gate With Village Wall	Current Condition	In ¹	Use	Aban	idoned	
Elements		Building Materials		Buildi	ing Meth	ods		
Entrance Gate		Concrete		C	Concrete			
Couplet		Written on Paper	Glu	ed to side	es of Entr	ance Gate		
Wall		Stone			Laying			
Additional Building Description (Optional)	The Entra outlook.	The Entrance Gate appears to be repaired with concrete while the stone wall remains its original outlook.						
Historical /Cultural Information (Optional)								
		Representative	Photo(s)					
Façade Other View(s) /								
Detail(s) (Optional):								
Recorded by Ka	thy Chan	Date 18/03/2014	Checked by	Anthony	Siu D a	ate 18/03/2	2014	




Survey Date:	18/03/2	014	-	1	Map No:	THO)3	
BH Item No.	TH03		Declared Monument	¥	es	1	No	
Name of BH	Two Earth	n Shrines	AMO Announced	4	2	3	No Grade	
Village/Town Name	Tung Hing	3	Grading	Propose	ed Monun	nent		
District	Tung Chu	ng, Lantau Island	Gov. Historic Sites	¥	e s	1	No	
Building Type	Earth Shr	ine	Land	Leaseholder Current Use				
Date of Construction	Not Know	n	Condition	Private Local Village				
Present Use	Earth Shr	ine	Current Condition	In	Use	Aban	doned	
Elements		Building Materials		Buildi	ng Metho	ods		
Door Shape Frame		Concrete	M	olded an	d Elected	on Altar		
Wall		Concrete	Built to Ap	illt to Approximately Half Height of the Door shape Frame				
Earth Gods		Stone + Ribbon	Laying or	n Rectan	gular Con	crete Platf	orms	
Door Gods		Painting on Paper		Glue	ed to Wall	ls		
Altar		Concrete	Built ir	nto raised	l Platform	s with Sta	irs	
Additional Building Description (Optional)		Earth Shrines are situated at soutl two shrines face away from the vil		f Tung H	ing village	e outside t	he village	
Historical /Cultural Information (Optional)								
		Representative I	Photo(s)			X		
Façade					大學學學學			
Other View(s) / Detail(s) (Optional):								
Recorded by Ka	thy Chan	Date 18/03/2014	Checked by	Anthony	Siu Da	ite 18/03/2	2014	




Survey Date:	18/03/2	014			Map No:	SLP0	1	
BH Item No.	SLP01		Declared Monument	¥	'es	1	No	
Name of BH	Earth Shri	ne	AMO Announced	4	2	3	No Grade	
Village/Town Name	Shek Lau	Po	Grading		ed Monur	ment		
District	Tung Chu	ng, Lantau Island	Gov. Historic Sites	¥	'es	1	No	
Building Type	Earth Shri	ne	Land	Lease	holder	Curre	nt User	
Date of Construction	Not Know	n	Condition	Pri	vate	Local	/illagers	
Present Use	Earth Shri	ne	Current Condition	In Use Abandoned				
Elements		Building Materials		Build	ing Meth	ods		
Earth Gods		Stone with Ribbon	l	aying stor	nes on To	p of Altar		
Altar		Concrete	Built into	Rectangul	ar Platfori	m, Painted	in Red	
Additional Building Description (Optional)	The Earth	Shrine is located at west er	nd of Shek Lau Po v	of Shek Lau Po village and built under a tree.				
Historical /Cultural Information (Optional)								
		Represent	ative Photo(s)	16.00				
Façade								
Other View(s) / Detail(s) (Optional):								
Recorded by Kat	thy Chan	Date 18/03/2014	Checked by	Anthony	Siu D a	ate 18/03/2	2014	




Survey Date:	18/03/2014			ſ	Map No:	SLP02	2	
BH Item No.	SLP02		Declared Monument	¥	'es	1	No	
Name of BH	Ancestral Hall		AMO Announced	4	2	3	No Grade	
Village/Town Name	Shek Lau Po		Grading	Propose	ed Monui	ument		
District	Tung Chung, Lantau Island		Gov. Historic Sites	¥	'es	1	No	
Building Type	Ancestral Hall		Land	Lease	holder	Curre	nt User	
Date of Construction	Not Known		Condition	Pri	vate	1	No	
Present Use	Vacant		Current Condition	In	Use	Aban	ndoned	
Elements	Building Materi	ials		Buildi	ng Meth	ods		
Roof Tile	Cannot be Observed due Vegetation	to Overgrown	Cannot be Ol	bserved o	due to O\	vergrown V	egetation	
Wall	Lime			Lir	ne Finish	ı		
Door	Metal + Paint	t	Metal Do	oor Painte	ed with Y	ellowish Br	rown	
Additional Building Description (Optional) Historical /Cultural Information (Optional)	It is an ancestral hall with Chinese characters written and weathering. It is possib堂).	on the pediment	and yet unrea	ıdable du	e to ove	rgrown of v	egetation/	
	R	epresentative F	Photo(s)					
Façade Other View(s) /			十件零件					
Other View(s) / Detail(s) (Optional):								
Recorded by Ka	thy Chan		Checked by	Anthony	Siu D a	ate 18/03/2	2014	




Survey Date:	18/03/2	014		ſ	Map No:	SLP0	3	
BH Item No.	SLP03		Declared Monument	¥	'es	1	No	
Name of BH	Earth Shr	ine	AMO Announced	1	2	3	No Grade	
Village/Town Name	Shek Lau	Ро	Grading	Propose	ed Monun	onument		
District	Tung Chu	ng, Lantau Island	Gov. Historic Sites	¥	' es	ı	No	
Building Type	Earth Shr	ine	Land	Lease	holder	Curre	nt User	
Date of Construction	Not Know	n	Condition	Pri	vate	Local '	Villagers	
Present Use	Earth Shr	ine	Current Condition	In	Use	Abar	ndoned	
Elements		Building Materials		Buildi	ing Metho	ods		
Earth God		Stone with Ribbon		Plac	ed on Alta	ar		
Door Gods		Painting on Paper		Glue	ed to Side	es		
Couplet		Writing on Paper		Glu	ed to Wa	II		
Altar		Concrete	Built i	nto Raise	ed Platforr	m and Sta	irs	
Additional Building Description (Optional)		rm-chair form earth shrine with t the entrance of Shek Lau Po	hrine with a tree grows at the center of the altar. The shrine is Lau Po village.					
Historical /Cultural Information (Optional)	village. Τι	符) placing at the altar means r unfu ceremony (<i>躉符儀式</i>) has b age. Offerings and incense stick d.	een practiced to	prevent a	dverse in	fluence or	n Feng sui	
		Representativ	e Photo(s)					
Façade								
Other View(s) / Detail(s) (Optional):			Tunfu (遵符)					
Recorded by Ka	thy Chan	Date 18/03/2014	Checked by	Anthony	Siu Da	nte 18/03/2	2014	




Survey Date:	18/03/2	014			Map No:	SLP0	4
BH Item No.	SLP04		Declared Monument	¥	'es		No
Name of BH	Ruined Vi	llage House near No. 31	AMO - Announced	4	2	3	No Grade
Village/Town Name	Shek Lau	Po	Grading	Propos	ed Monur	ment	
District	Tung Chu	ng, Lantau Island	Gov. Historic Sites	¥	′es		No
Building Type	Residentia	al Houses	Land	Lease	eholder	Curre	ent User
Date of Construction	Not Know	n	Condition	Pri	vate		No
Present Use	Vacant		Current Condition	In	Use	Abar	ndoned
Elements		Building Materials		Build	ing Meth	ods	
Roof Tile		Red Tile	Conc	ave, Cyli	ndrical Til	le Combin	ed
Tile End		Grey Cylindrical Tile		With	out Dripp	ers	
Wall	C	Granite Block + Concrete	Concre	te Fill In	Gaps Of (Granite Blo	ocks
Window	(Concrete + Metal Railing	Recta	angular V	Vindow O	pening Typ	ре
Door		Timber	Rectangula	ar Door C	Opening T	Type + Flus	sh Door
Additional Building Description (Optional)		-room-one-courtyard type village has collapsed. Vegetation grows			nape gabl	le walls. C	ne side of
Historical /Cultural Information (Optional)							
		Representative	Photo(s)	~7000000	7.00		
Façade							
Other View(s) / Detail(s) (Optional): Back View							
Recorded by Ka	athy Chan	Date 18/03/2014	Checked by	Anthony	Siu D a	ate 18/03/2	2014




Survey Date:	18/03/2	014		N	Лар No:	SLP05	5			
BH Item No.	SLP05		Declared Monument	Yes		No				
Name of BH	Village Ho	ouse near No. 35	AMO Announced	4	2	3	No Grade			
Village/Town Name	Shek Lau	Po	Grading	Proposed Monument						
District	Tung Chu	ng, Lantau Island	Gov. Historic Sites	Yes		No				
Building Type	Residentia	al house	Land	Leaseholder		Curre	Current User			
Date of Construction	Not know	า	Condition	Priv	vate	Local Villagers				
Present Use	Uncertain		Current Condition	In Use		Half Abandoned				
Elements		Building Materials		Building Methods						
Roof Tile		Red Tile	Concave, Cylindrical Tile Combined							
Tile End		Grey Cylindrical Tile	Without Drippers							
Wall		Lime	Lime Finish							
Door		Timber	Rectangular Door Opening Type + Flush Door							
Additional Building Description (Optional) Historical										
/Cultural Information (Optional)										
		Representative	Photo(s)							
Façade										
Other View(s) / Detail(s) (Optional):										
Recorded by Kathy Chan		Date 18/03/2014	Checked by	Anthony Siu Date 18/03/2		2014				




Survey Date:		Map No: <u>SLP06</u>									
BH Item No.	SLP06	SLP06		Yes		No					
Name of BH	Village Ho	ouse No. 35	AMO Announced	4	2	3	No Grade				
Village/Town Name	Shek Lau	Ро	Grading	Proposed Monument							
District	Tung Chu	ing, Lantau Island	Gov. Historic Sites	Yes		No					
Building Type	Residentia	Residential House Land Leasel				Older Current User					
Date of Construction	Mid to Lat	te 19 th Century	Condition	Pri	vate	Local Villagers					
Present Use	Vacant		Current Condition	ŀn⊣	Use	Half Ab	Half Abandoned				
Elements		Building Materials		Building Methods							
Roof Tile		Red Tile	Conc	Concave, Cylindrical Tile Combined							
Tile End		Grey Cylindrical Tile		Without Drippers							
Wall		Lime	Lime Finish								
Window	Concrete + Metal Railing Rectangular Window Opening Type										
Door	Timber Rectangular Door Opening Type + Flush Door										
Additional Building Description (Optional)	It is a two-storey building with a pitched roof and a balcony on the second floor. A single storey building with a pitched roof attaches to its side. Window of the single storey building has a small rectangular window canopy.										
Historical /Cultural Information (Optional)	Since modern concrete was only introduced into Hong Kong region in Late 19 th century, buildings before then adopted traditional building materials, which could not support the buildings that were over two stories. This two-storey building might thus be built around Mid to Late 19 th century.										
		Representative	Photo(s)	21. O'CM							
Façade Other View(s) /											
Detail(s) (Optional):			 T		1						
Recorded by Kathy Chan		Date 18/03/2014	Checked by	Anthony	Siu D a	ate 18/03/2	2014				




Survey Date:	18/03/2	014		_		Мар No:	SLP0	7				
BH Item No.	SLP07			Declared Monument	Yes No							
Name of BH	Earth Shr	ine		AMO Announced	4	2	3	No Grade				
Village/Town Name	Shek Lau	Ро		Grading	Propose	ed Monum	nent					
District	Tung Chu	ıng, Lantau Island		Gov. Historic Sites	¥	es	1	No				
Building Type	Earth Shr	ine		Land	Lease	holder	Curre	nt User				
Date of Construction	Not Know	'n		Condition	Pri	vate	Local	Villagers				
Present Use	Earth Shr	ine		Current Condition	In I	Use	Abar	idoned				
Elements		Building Materia	als		Buildin	g Method	ds					
Earth Gods	Stor	ne with Paper Dec	coration		Place	d on Altar						
Door Gods		Painting on Pape	er		Glued to	Sides of A	Altar					
Couplet		Writing on Pape	er		Glued to	Wall of Al	ltar					
Altar		Concrete		Built int	o Raised	Platform	with Stairs	S				
Additional Building Description (Optional) Historical /Cultural Information (Optional)		ek Lau Po village.		m and under a bai	nyan tree	. The shri	ne is situa	ated at the				
		F	Representativ	e Photo(s)	THUN SO							
Façade												
Other View(s) / Detail(s) (Optional): Built under a Banyan Tree	thy Chan	Date 19/02/2014		Chacked by An	thony Sim	Data 1	B/D2/2044					
Recorded by Ka	iny Chan	Date 18/03/2014	+	Checked by An	mony Siu	Date 18	8/03/2014					




Survey Date:	18/03/2	014		١	Map No:	SLP08	3			
BH Item No.	SLP08		Declared Monument	Yes No						
Name of BH	Earth Shr	ine	AMO Announced	4	2	3	No Grade			
Village/Town Name	Shek Lau	Po	Grading	Propose	ed Monur	ment				
District	Tung Chu	ing, Lantau Island	Gov. Historic Sites	¥	'es	1	No			
Building Type	Earth Shr	ine	Land	Lease	holder	Curre	nt User			
Date of Construction	Not Know	'n	Condition	Pri	vate	Local	Villagers			
Present Use	Earth Shr	ine	Current Condition	In	Use	Abar	ndoned			
Elements		Building Materials		Buildi	ing Meth	ods				
Earth Gods	Stone wit	th Ribbon and Paper Decoration		Placed on Altar						
Altar		Concrete		Enclosed on Three Sides						
Additional Building Description (Optional)		plified arm-chair form earth shrir e other earth shrine under a ban		at the exit	of Shek	Lau Po vil	lage, right			
Historical /Cultural Information (Optional)										
		Representative	Photo(s)		Σ					
Façade										
Other View(s) / Detail(s) (Optional):										
Recorded by Ka	thy Chan	Date 18/03/2014	Checked by Anthony Siu Date 18/03/2014							




Map No: SLP09 Survey Date: 18/03/2014 Declared BH Item No. SLP09 Yes No **Monument** No Name of BH Ruined Village House near No.31 4 2 3 **AMO** Grade **Announced** Village/Town Grading Shek Lau Po **Proposed Monument** Name Gov. **District** Tung Chung, Lantau Island **Historic** Yes No **Sites Building Type** Leaseholder **Current User** Residential House Land Date of Condition Not Known Private Local Villagers Construction Current **Present Use** Storage In Use **Abandoned** Condition **Elements Building Materials Building Methods** Roof Tile Asbestos (Suspected) Asbestos (Suspected) Corrugated Shingle Wall Stone foundation + Concrete Concrete Finish On Upper Half of the Wall Door Timber Rectangular Door Opening Type + Flush Door Additional **Building Description** (Optional) Historical /Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional): Recorded by Kathy Chan Date 18/03/2014 Date 18/03/2014 Checked by Anthony Siu




Survey Date:	18/03/2	014			Map No:	SLP	010
BH Item No.	SLP010		Declared Monument	¥	'es		No
Name of BH	Earth Shr	ine	AMO Announced	1	2	3	No Grade
Village/Town Name	Shek Lau	Po	Grading	Propos	ed Monum	nent	
District	Tung Chu	ng, Lantau Island	Gov. Historic Sites	¥	′es		No
Building Type	Earth Shr	ine	Land	Lease	eholder	Curre	ent User
Date of Construction	Not Know	'n	Condition	Pri	vate	Local	Villagers
Present Use	Storage		Current Condition	In	Use	Abar	ndoned
Elements		Building Materials		Build	ing Metho	ods	
Earth Gods	St	one with Shell Decoration	Fi	xed with	Concrete	on Altar	
Altar		Concrete	Built into R		atform + Pa ite Colours		h Red &
Gravestone	avestone Stone + Paint Fixed with Co						
Additional Building Description (Optional) Historical /Cultural	The earth character are "清顯	arth shrine with a relocated graves god stone is decorated with seas s, however, most of them have bee :誥封六品二十世祖孝王公" (from items are put on the altar.	shells. On the en weathered.	gravesto The reco	ne, there a	are carve emaining	d Chinese characters
Information (Optional)							
	I	Representative I	Photo(s)				
Façade							
Other View(s) / Detail(s) (Optional): 1. Earth god (left) 2. Relocated Gravestone (right)				September 19 Comments of the C	A popular at mis resulted		
Recorded by Kathy ChanDate 18/03/2014Checked by Anthony SiuDate 18/03/2014							2014



MK01 Survey Date: 19/01/2014 Map No: Declared BH Item No. Yes MK01 No Monument No Name of BH Village Houses No.2 & 3 1 2 3 AMO Grade **Announced** Village/Town Grading Mok Ka Proposed Monument Name Gov. **District Historic** Yes No Tung Chung, Lantau Island **Sites Building** Residential House Leaseholder **Current User Type** Land Date of Condition Not Known Private Local Villagers Construction Current **Present Use** Residential House In Use **Abandoned** Condition **Elements Building Materials Building Methods** Roof Tile **Grey Tile** Concave, Cylindrical Tile Combined Grey Cylindrical Tile Tile End Without Drippers No.3: Red Brick + Lime Lime Finish On Red Brick Wall No.2: Granite Block Mortar Fills In Gaps Between Granite Blocks Door Metal + Glass Additional They are one-room-one hall type building with a shared courtyard. They are situated next to the **Building Description** modern ancestral hall building Mok Yu Sang Ancestral Hall (莫裕生堂). (Optional) Historical /Cultural Information (Optional) Representative Photo(s) Façade Other View(s) Detail(s) (Optional): Recorded by Chris Day Date 19/01/2014 Checked by Anthony Siu Date 18/03/2014




	Survey Date:	19/01/2	014	_	1	Map No:	MK0	2
Name of BH	BH Item No.	MK02			¥	'es	1	No
Mame District Tung Chung, Lantau Island Building Type Residential House Land Construction Present Use Residential House Leaseholder Current Condition Private Local Villager Current Condition Residential House Current Condition Residential House Elements Building Materials Building Methods Roof Tile Grey Tile Grey Tile Concave, Cylindrical Tile Combined Tile End Grey Cylindrical Tile Without Drippers Wall Stone + Brick + Concrete Concrete Finish On Stone And Brick Wall Door Timber Rectangular Door Opening Type + Flush Door - Rectangular Block Door Drum Additional Building Description (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional): Cother View(s) / Detail(s) (Optional):	Name of BH			_	4	2	3	No Grade
District Tung Chung, Lantau Island Historic Sites Yee No		Mok Ka		Grading	Propose	ed Monum	nent	
Date of Construction Present Use Residential House Residential House Condition Residential House Residential House Concave, Cylindrical Tile Combined Concave, Cylindrical Tile Combined Residential Tile Concave, Cylindrical Tile Combined Tile End Grey Cylindrical Tile Residential Tile Concave, Cylindrical Tile Combined Tile End Grey Cylindrical Tile Rectangular Door Opening Type + Flush Door Rectangular Block Door Drum Rectangular Block Door Drum Residential Block Door Drum Representative Photo(s) Cother View(s) / Detail(s) (Optional):	District	Tung Chu	ng, Lantau Island	Historic	¥	'es	ı	No
Date of Construction Private Residential House Current Condition Residential House Current Condition Residential House Current Condition Residential House Residential Residential House Residential Residen	Building Type	Residenti	al House	Land	Lease	holder	Curre	nt User
Elements Building Materials Building Methods Roof Tile Grey Tile Concave, Cylindrical Tile Combined Tile End Grey Cylindrical Tile Without Drippers Wall Stone + Brick + Concrete Concrete Finish On Stone And Brick Wall Door Timber Rectangular Door Opening Type + Flush Door Rectangular Block Door Drum Additional Building Description (Optional) Historical / Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):		Not Know	n		Priv	vate	Local '	Villagers
Roof Tile Grey Tile Concave, Cylindrical Tile Combined Tile End Grey Cylindrical Tile Without Drippers Wall Stone + Brick + Concrete Concrete Finish On Stone And Brick Wall Door Timber Rectangular Door Opening Type + Flush Door Rectangular Block Door Drum Additional Building Description (Optional) Historical / Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Present Use	Residenti	al House		In l	Use	Abar	ndoned
Tile End Grey Cylindrical Tile Without Drippers Wall Stone + Brick + Concrete Concrete Finish On Stone And Brick Wall Door Timber Rectangular Door Opening Type + Flush Door Rectangular Block Door Drum Additional Building Description (Optional) Historical / Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Elements		Building Materials		Buildi	ng Metho	ods	
Wall Door Timber Rectangular Door Opening Type + Flush Door Rectangular Block Door Drum Additional Building Description (Optional) Historical /Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Roof Tile		Grey Tile	Conc	ave, Cylir	ndrical Tile	e Combine	ed
Door Timber Rectangular Door Opening Type + Flush Door Rectangular Block Door Drum Additional Building Description (Optional) Historical /Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Tile End		Grey Cylindrical Tile		Witho	out Drippe	ers	
Additional Building Description (Optional) Historical (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional): Rectangular Block Door Drum Rectangular Block Door Drum Rectangular Block Door Drum	Wall	S	Stone + Brick + Concrete	Concret	e Finish C	On Stone	And Brick	Wall
Building Description (Optional) Historical /Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Door		Timber					n Door +
Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Building Description (Optional)							
Façade Other View(s) / Detail(s) (Optional):	Information							
Other View(s) / Detail(s) (Optional):			Representative	Photo(s)				
Detail(s) (Optional):								
Recorded by Chris Day Date 19/01/2014 Checked by Anthony Sir Date 19/03/2014	Detail(s)							
Treating by Anthony Sid Pate 10/03/2014	2014							




MK03 Survey Date: 19/01/2014 Map No: Declared BH Item No. MK03 Yes No **Monument** No Name of BH Mok Yu Sang Ancestral Hall (莫裕生堂) 4 2 3 **AMO** Grade Announced Village/Town Grading Mok Ka **Proposed Monument** Name Gov. Historic **District** Tung Chung, Lantau Island Yes No **Sites Building Type** Ancestral Hall Leaseholder **Current User** Land Date of Condition Private Local Villagers Not Known Construction Current **Present Use** Residential House In Use **Abandoned** Condition **Elements Building Materials Building Methods** NA Roof Tile NA NA NA Tile End NA NA Wall NA NA Door Additional **Building** It is a modern building. **Description** (Optional) **Historical** /Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional): Recorded by Chris Day Date 19/01/2014 Checked by Anthony Siu Date 18/03/2014



Survey Date:	19/01/2	014		_		Map No:	MK0	4					
BH Item No.	MK04			Declared Monument									
Name of BH	Stone Brid	dge		AMO Announced	4	2	3	No Grade					
Village/Town Name	Mok Ka			Grading	Propose	ed Monui	ment						
District	Tung Chu	ng, Lantau Island		Gov. Historic Sites	¥	'es	1	No					
Building Type	Bridge			Land	Lease	holder	Curre	nt User					
Date of Construction	Not Know	n		Condition	Pri	vate	Local	Villagers					
Present Use	Bridge			Current Condition	In	Use	Abar	idoned					
Elements		Building Materials			Buildi	ing Meth	ods						
Bridge		Stone		Laying across Stream in single span									
Step		Stone		Layii	ng at Eac	h Side o	f the Bridge	Э					
Additional Building Description (Optional)													
Historical /Cultural Information (Optional)													
		Repre	esentative I	Photo(s)									
Façade													
Other View(s) / Detail(s) (Optional):													
Recorded by Ch	ris Day	Date 19/01/2014		Checked by	Anthony	Siu D a	ate 18/03/2	2014					




Survey Date:	19/01/2	014		I	Map No:	MK0	5				
BH Item No.	MK05		Declared Monument	Yes No							
Name of BH	Earth Shr	ine	AMO Announced	1	2	3	No Grade				
Village/Town Name	Mok Ka		Grading	Propos	ed Monu	ment					
District	Tung Chu	ing, Lantau Island	Gov. Historic Sites	¥	'es	1	No				
Building Type	Earth Shr	ine	Land	Lease	holder	Curre	nt User				
Date of Construction	Not Know	'n	Condition	Pri	vate	Local	/illagers				
Present Use	Earth Shr	ine	Current Condition	In	Use	Aban	doned				
Elements		Building Materials		Build	ing Meth	nods					
Door Shape Frame		Concrete	Molded And I		n Altar + Writing	Carved an	d Painted				
Couplet		Concrete Molded And Elected Besides Door Shape Fra Carved and Painted on Concrete Tablets									
Altar		Concrete		Built Ir	nto Arm-(Chair					
Earth God		Stone		Pla	ce on Alt	ar					
Additional Building Description (Optional)											
Historical /Cultural Information (Optional)											
		Representative	Photo(s)		72 * 500	ii ii					
Façade Other View(s) /		处胜人與有失事 地胜人與有失事	大地為物								
Detail(s) (Optional):					ı						
Recorded by Ch	by Chris Day Date 19/01/2014 Checked by Anthony Siu Date 18/03/2014										




Survey Date:	19/01/2	014	_		Map No:	MK0	6					
BH Item No.	MK06		Declared Monument	Yes No								
Name of BH	Mok Ka E	ntrance Gate	AMO Announced	4	2	3	No Grade					
Village/Town Name	Mok Ka		Grading	Propose	ed Monur	ment						
District	Tung Chu	ng, Lantau Island	Gov. Historic Sites	¥	'es	1	No					
Building Type	Entrance	Gate	Land	Lease	holder	Curre	nt User					
Date of Construction	Not Know	n	Condition	Pri	vate	Local	Villagers					
Present Use	Entrance	Gate	Current Condition	In	Use	Abar	idoned					
Elements		Building Materials		Buildi	ing Meth	ods						
Gate		Concrete		Concr	ete Finish	hing						
Wall		Stone+ Mortar	Fille	ed Mortar	in betwe	en Stones						
Couplet	t Paint Carved and Painted on Concrete											
Additional Building Description (Optional) Historical												
/Cultural Information (Optional)												
	I	Representative	Photo(s)									
Façade												
Other View(s) / Detail(s) (Optional):												
Recorded by Ch	ris Day	Date 19/01/2014	Checked by	Anthony	Siu D a	Recorded by Chris DayDate 19/01/2014Checked by Anthony SiuDate 18/03/2014						




BH Item No.	Survey Date:	19/01/2	014	-	ſ	Map No	: <u>MK0</u>	7	
Name Or BH Stone Kullis Announced Carading Representative Photo(s) Façade Other View(s) / Detail(s) Other View(s) / Detail(s) District Stone Rullis Announced Grading Representative Photo(s) Announced Grading Representative Photo(s) Preposeed Monument Representative Photo(s) Announced Grading Representative Photo(s) Proposeed Monument Representative Photo(s) Abandoned Current Condition Condition Private Local Villagers Laying Abandoned Laying Abandoned Laying Abandoned Current Condition Private Local Villagers Laying Abandoned Current User Abandoned Current Condition Condition In User Abandoned Current Condition Current User Private Local Villagers Abandoned Land Current User Abandoned Current Condition Façade Private Local Villagers Abandoned Current Condition Private Local Villagers Abandoned Current User Abandoned Current Use	BH Item No.	MK07			¥	es	1	No	
Village/Town Name Mok Ka Grading Preposeed Menument	Name of BH	Stone Rui	ins		4	2	3		
District Tung Chung, Lantau Island Historic Sites Sites No Building Type Not Known Land Condition Private Local Villagers Present Use Abandoned Current Condition In Use Abandoned Elements Building Materials Building Materials Laying Additional Building Description (Optional) Historical / Coultural Information (Optional) Façade Other View(s) / Detail(s) (Optional):		Mok Ka			Propose	ed Monu	ıment		
Date of Construction Present Use Represent Use Represent Use Represent Use Represent Use Representative Photo(s) Representative Photo(s) Condition Private Local Villagers Abandoned Laying Abandoned Laying Additional Building Methods They are short stone walls built into rectangular shape. Representative Photo(s) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	District	Tung Chu	ng, Lantau Island	Historic	¥	'es	1	No	
Construction Present Use Abandoned Current Condition In-Uee Abandoned Elements Building Materials Wall Stone Laying Additional Building Description (Optional) Historical /Cultural information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):		Not Know	n	Land	Lease	holder	Curre	nt User	
Elements Building Materials Building Methods Wall Stone Laying Additional Building Description (Optional) Historical / Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):		Not Know	n		Pri	vate	Local	Villagers	
Wall Stone Laying Additional Building Description (Optional) Historical / Cultural Information (Optional) Façade Other View(s) / Detail(s) (Optional):	Present Use	Abandone	ed		ln-	Use	Aban	ndoned	
Additional Building Description (Optional) Historical / Cultural Information (Optional) Façade Other View(s) / Detail(s) (Optional): They are short stone walls built into rectangular shape.	Elements		Building Materials		Buildi	ng Metl	hods		
Building Description (Optional) Historical /Cultural Information (Optional) Façade Other View(s) / Detail(s) (Optional): They are short stone walls built into rectangular shape. Other View(s) / Detail(s) (Optional):	Wall		Stone			Laying			
Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Building Description (Optional)	They are	short stone walls built into rectang	gular shape.					
Façade Other View(s) / Detail(s) (Optional):	/Cultural Information								
Other View(s) / Detail(s) (Optional):			Representative	Photo(s)			F 75 F W	THEORY	
Detail(s) (Optional):	Façade								
	Detail(s)	40000				ANT		and the second	
		ris Day	Date 19/01/2014	Checked by	hecked by Anthony Siu Date 18/03/2014				




Name of BH Ruined village House Next to No. 6 Name of BH Ruined village House Next to No. 6 Name of BH Ruined village House Next to No. 6 AMO Announced Grading Preposed Montment Private No	Survey Date:	18/03/2	014			Map No	o: SMK	(01					
Village/Town Name Shek Mun Kap Shek Mun Ka	BH Item No.	SMK01			Yes No								
Village/Town Name Shek Mun Kap Grading Proposed Monument District Tung Chung, Lantau Island Historic Sites No Building Type Residential House Land Condition Leaseholder Current User Date of Construction Not Known Condition Private No Present Use Residential House Current Condition Abandoned Elements Building Materials Building Methods Roof Tile Grey Tile Concave, Cylindrical Tile Combined Tile End Grey Cylindrical Tile Without Drippers Wall Granite Block Mortar Fill In Gaps Between Granite Blocks Door Timber Rectangular Door Opening Type + Flush Door Additional Building Description (Optional) """ Historical / (Cultural Information (Optional) """ Façade Façade Other View(s) / Detail(s) (Optional):	Name of BH	Ruined vil	llage House Next to No. 6	_	4	2	3						
District Tung Chung, Lantau Island Historic Sites Yee No Building Type Residential House Land Condition Leaseholder Current User Date of Construction Not Known Condition Private No Present Use Residential House Current Condition In-use Abandoned Elements Building Materials Building Methods Roof Tile Grey Cylindrical Tile Without Drippers Wall Granite Block Mortar Fill In Gaps Between Granite Blocks Door Timber Rectangular Door Opening Type + Flush Door Additional Building Description (Optional)		Shek Mur	ı Кар		Propos	ed Moni	ument						
Date of Construction Present Use Residential House Residential Methods Roof Tile Residential Mithout Drippers Wall Granite Block Mortar Fill In Gaps Between Granite Blocks Rectangular Door Opening Type + Flush Door Additional Building Rescription (Optional) Representative Photo(s) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	District	Tung Chu	ng, Lantau Island	Historic	¥	'es		No					
Date of Construction Not Known Condition Private No Present Use Residential House Current Condition In use Abandoned Elements Building Materials Building Methods Roof Tile Grey Tile Concave, Cylindrical Tile Combined Tile End Grey Cylindrical Tile Without Drippers Wall Granite Block Mortar Fill In Gaps Between Granite Blocks Door Timber Rectangular Door Opening Type + Flush Door Additional Building Description (Optional)	Building Type	Residentia	al House	Land	Lease	eholder	Curre	ent User					
Elements Building Materials Building Methods Roof Tile Grey Tile Concave, Cylindrical Tile Combined Tile End Grey Cylindrical Tile Without Drippers Wall Granite Block Mortar Fill In Gaps Between Granite Blocks Door Timber Rectangular Door Opening Type + Flush Door Additional Building Description (Optional) Historical //Cultural Information (Optional) Façade Other View(s) / Detail(s) (Optional):		Not Know	n	Condition	Pri	vate		No					
Roof Tile Grey Tile Concave, Cylindrical Tile Combined Tile End Grey Cylindrical Tile Without Drippers Wall Granite Block Mortar Fill In Gaps Between Granite Blocks Door Timber Rectangular Door Opening Type + Flush Door Additional Building Description (Optional) Historical /Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Present Use	Residentia	al House		- In	use	Abaı	ndoned					
Tile End Grey Cylindrical Tile Without Drippers Wall Granite Block Mortar Fill In Gaps Between Granite Blocks Door Timber Rectangular Door Opening Type + Flush Door Additional Building Description (Optional) Historical /Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Elements		Building Materials		Build	ing Met	hods						
Wall Granite Block Mortar Fill In Gaps Between Granite Blocks Door Timber Rectangular Door Opening Type + Flush Door Additional Building Description (Optional) Historical / Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Roof Tile		Grey Tile	Conc	ave, Cyli	ndrical T	Γile Combin	ed					
Door Timber Rectangular Door Opening Type + Flush Door Additional Building Description (Optional) Historical /Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Tile End		Grey Cylindrical Tile		With	out Drip	pers						
Additional Building Description (Optional) Historical /Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Wall		Granite Block	Mortar Fi	ll In Gaps	s Betwee	en Granite I	Blocks					
Building Description (Optional) Historical /Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Door		Timber	Rectangula	ar Door C	pening	Type + Flus	sh Door					
Cultural Information (Optional) Representative Photo(s) Façade Other View(s) / Detail(s) (Optional):	Building Description (Optional)												
Façade Other View(s) / Detail(s) (Optional):	/Cultural Information												
Façade Other View(s) / Detail(s) (Optional):		T	Representativ			345							
Detail(s) (Optional):						報							
Recorded by Kathy ChanDate 18/03/2014Checked by Anthony SiuDate 18/03/2014	Detail(s)												
	Recorded by Kathy ChanDate 18/03/2014Checked by Anthony SiuDate 18/03/2014												




Survey Date:	18/03/2	014	_		Map No:	SMK	02			
BH Item No.	SMK02		Declared Monument	Yes No						
Name of BH	Village Ho	ouse No. 8	AMO Announced	4	2	3	No Grade			
Village/Town Name	Shek Mur	п Кар	Grading	Propos	ed Monur	ment				
District	Tung Chu	ing, Lantau Island	Gov. Historic Sites	¥	'es	1	No			
Building Type	Residentia	al House	Land	Lease	holder	Curre	nt User			
Date of Construction	Not Know	'n	Condition	Pri	vate	Local '	Villagers			
Present Use	Residentia		Current Condition		Use		ndoned			
Elements		Building Materials		Buildi	ing Meth	ods				
Roof Tile		Grey Tile	Conc	ave, Cylii	ndrical Til	e Combine	ed			
Tile End		Grey Cylindrical Tile		With	out Dripp	ers				
Wall	G	Granite Block + Concrete	Concrete F	rete Fill In Gaps Between Granite Bloo						
Door		Timber	Rectangula	ctangular Door Opening Type + Flush D						
Additional Building Description (Optional)		age house with a balcony and flast made of metal and glass and is the				ched roof	Rear Hall.			
Historical /Cultural Information (Optional)										
		Representative	Photo(s)							
Façade										
Other View(s) / Detail(s) (Optional): Diagonal View	Thy Chap Date 19/03/2014 Checked by Asthony Six Date 19/03/2014									
Recorded by Kathy ChanDate 18/03/2014Checked by Anthony SiuDate 18/03/2014					2014					




Survey Date:	18/03/	2014	-		Map No:	SMK	03			
BH Item No.	SMK03		Declared Monument	Yes No						
Name of BH	Ruined \	/illage Houses near No. 12 A	AMO Announced	4	2	3	No Grade			
Village/Town Name	Shek Mu	n Kap	Grading	Propose	ed Monumer	nt				
District	Tung Ch	ung, Lantau Island	Gov. Historic Sites	2	Yes		No			
Building Type	Resident	ial House	Land	Leas	eholder	Curr	ent User			
Date of Construction	Not Know	wn	Condition	Pr	rivate		No			
Present Use	Vacant		Current Condition	In) use	Aba	ındoned			
Elements		Building Materials		Buildir	ng Methods	\$				
Not observable	due to ass	ess problem								
Additional Building Description (Optional)										
Historical /Cultural Information (Optional)										
Façade		Representativ								
Other View(s) / Detail(s) (Optional):		ANDON								
Recorded by Chan	Kathy	Date 18/03/2014	Checked by A	nthony Si	u Date	18/03/20)14			




18/03/2014 SMK04 Survey Date: Map No: **Declared** BH Item No. SMK04 No Yes **Monument** No Name of BH Village house Next to No. 10 4 2 3 **AMO** Grade Announced Village/Town Grading Shek Mun Kap **Proposed Monument** Name Gov. **District Historic** Yes No Tung Chung, Lantau Island **Sites Building Type** Leaseholder **Current User** Residential house Land Date of Condition Not Known Private Local Villagers Construction Current **Present Use** Residential house In Use **Abandoned** Condition **Elements Building Materials Building Methods** Roof Tile Concave, Cylindrical Tile Combined **Grey Tile** Tile End Grey Cylindrical Tile Without Drippers Wall Granite Block + Concrete Concrete Fill in Gaps Between Granite Blocks Door Timber Rectangular Door Opening Type + Flush Door Additional It is a village house with a balcony and flat-rooted First Hall adjoining a pitched roof Rear Hall. **Building** Description Window is made of metal and glass and is with a concrete window canopy. (Optional) Historical /Cultural Information (Optional) Representative Photo(s) Façade No enough space to photograph façade view Other View(s) / Detail(s) (Optional): Date 18/03/2014 Recorded by Kathy Chan Checked by Anthony Siu Date 18/03/2014




Survey Date:	18/03/2	<u>014 </u>		Ī	Map No	o: <u>Sl</u>	ИK	05			
BH Item No.	SMK05		Declared Monument								
Name of BH	Tai Wong	Ye (大王爺) Earth Shrine	AMO Announced	4	2	3		No Grade			
Village/Town Name	Shek Mur	ı Кар	Grading	Propos	ed Mon	nument					
District	Tung Chu	ng, Lantau Island	Gov. Historic Sites	¥	'es		I	No			
Building Type	Earth Shr	ine	Land	Lease	holder	r Cu	rre	nt User			
Date of Construction	Not Know	n	Condition	Pri	vate	Loc	al '	Villagers			
Present Use	Earth Shr	ine	Current Condition	In	Use	Al	ar	idoned			
Elements		Building Materials		Buildi	ing Me	thods					
Huge Rock		Stone		in	Situ Ro	ock					
Earth Gods		Stone with Ribbon		Plac	ed on A	Altar					
Door Gods		Painting on Paper		Glued	l to Alta	ır Wall					
Couplet		Stone	Ca	rved And	Painte	d on Table	ets				
Altar		Concrete + Stone				d Platforr luge Rock		A Wall			
Additional Building Description (Optional) Historical /Cultural Information (Optional)											
		Representative	Photo(s)								
Façade Other View(s) /		主见庇佑為民生	◆ 王大 大徒扶持家宅								
Detail(s) (Optional):		D		•	<u>. T.</u>	.	· C *	2044			
Recorded by Ka	Recorded by Kathy Chan Date 18/03/2014 Checked by Anthony Siu Date 18/03/2014										



Survey Date:							06			
BH Item No.	SMK06		Declared Monument	Yes		No				
Name of BH	Earth Shri	ne	AMO Announced	4	2	3	No Grade			
Village/Town Name	Shek Mun	Кар	Grading	Propose	ed Monur	ment				
District	Tung Chu	ng, Lantau Island	Gov. Historic Sites	Yes I			No			
Building Type	Earth Shri	ne	Land	Leaseholder Currei			nt User			
Date of Construction	Not Know	n	Condition	Private		Local	Local Villagers			
Present Use	Earth Shri	ne	Current Condition	In Use		Abandoned				
Elements		Building Materials		Buildi	ng Meth	ods				
Earth God		Stone with Ribbon		Placed on Altar						
Door Shape Frame	5	Stone Tablet + Concrete		Built on Altar						
Altar Platform	5	Stone Tablet + Concrete	В	Built into a Raised Platform						
Additional Building Description (Optional) Historical /Cultural Information (Optional)										
		Representat	tive Photo(s)	No.						
Façade Other View(s) /										
Detail(s) (Optional):	Abor Ole and	Data 40/00/0044	Charlett	A	c: <u>-</u>	10/00/2	004.4			
Recorded by Ka	iny Chan	Date 18/03/2014	Checked by	Antnony	oiu D a	ite 18/03/2	:U14			



Survey Date:	18/03/2014				Map No: SMK07				
BH Item No.	SMK07		Declared Monument	Yes		1	No		
Name of BH	Entrance	Gate, Shek Mun Kap	AMO Announced	4	2	3	No - Grade		
Village/Town Name	Shek Mur	n Кар	Grading	Propose	ed Monu	ment	nt		
District	Tung Chu	ing, Lantau Island	Gov. Historic Sites	Yes		1	No		
Building Type	Entrance	Gate	Land	Leaseholder Current			nt User		
Date of Construction	Probably	Built around 1880	Condition	Private		Local \	Local Villagers		
Present Use	Entrance	Gate	Current Condition	In Use		Aban	Abandoned		
Elements		Building Materials		Building Methods					
Gate	S	tone + Mortar (?) + Lime	Rectang	gular Ope	ning Typ	oe +Lime Fi	nish		
Name Broad		Mortar (?)		Molded + Painted					
Couplet		Stone Tablets		Carved + Painted					
Wall	Stone + Mortar Mortar Fills in Gaps Between Stone Blocks						llocks		
Additional Building Description (Optional) Historical /Cultural	The entrance gate was confirmed a Grade 3 historic building on 31 Aug 2010. It has been renovated by repainting the surface and replacing the couplet into tablet form. The entrance gate was built for <i>fung shui</i> and defence purposes. They protected the villagers								
Information (Optional)	from the attack of pirates and bandits (AMO's 1444 Historic Building Appraisal).								
	T	Representati	ve Photo(s)		2000	F & MK - 1/2			
Façade Other View(s) /									
Detail(s) (Optional):									
Recorded by Ka	thy Chan	Date 18/03/2014	Checked by	Anthony	Siu D	Date 18/03/2014			



Survey Date:	18/03/2014				Map No: <u>SMK08</u>							
BH Item No.	SMK08			Declared Monument	Yes		No					
Name of BH	Yuen Tan	Temple (玄壇古廟)		AMO Announced	4	2	3	No Grade				
Village/Town Name	Shek Mun	Кар		Grading	Proposed Monument							
District	Tung Chu	ng, Lantau Island		Gov. Historic Sites	Yes No			No				
Building Type	Temple			Land	Leaseholder Current U			nt User				
Date of Construction	Not Know	n, Renovated in 200	0	Condition	Private		Local	Local Villagers				
Present Use	Temple			Current Condition	In Use		Abandoned					
Elements		Building Materials	S		Building Methods							
Roof Tile		Grey Tile + Red Tile	е	Concave, Cylindrical Combined								
Tile End		Cylindrical Tile			Witho	ut Drippi	ngs					
Wall		Concrete		Concrete Finish					Concrete Fir			
Door		Timber + Granite		Recessed Entrance + Rectangular Opening Type + Flush Door								
Additional Building Description (Optional) Historical												
/Cultural Information (Optional)	The present temple was a later rebuilt (in 2000) as the village experienced several outbreaks of plagues (AMO's 1444 Historic Building Appraisal). The temple serves Fuhu Yuen Tan (伏虎玄壇).											
(Optional)		Ren	resentative F	Photo(s)								
Façade												
Other View(s) / Detail(s) (Optional): Fuhu Yuen Tan (伏虎玄壇).												
Recorded by Ka	thy Chan	Date 18/03/2014		Checked by	Anthony	Siu D a	Date 18/03/2014					

