

Appendix 12.4

Plate



Plate 1 – Undivided meta-sandstone with meta-conglomerate and phyllite hills



Plate 2 - View of the nursery area looking south; notice the water pipe in the background



Plate 3 – View of the nursery area toward the west; notice the elevated road on the right



Plate 4 – View of within 50m of the study area looking southeast



Plate 5 – View of the fill area to the south



Plate 6 – View of the water pipes looking west to the south of the assessment area



Plate 7 – View of north of the eastern part of the licence area with alluvial area to right next to rubble filled area



Plate 8 – View of alluvial area along the east of the Licence Area looking north, stream runs along the base of the hill (top right corner)