






EXISTING CONDITIONS



DAY 1 WITHOUT MITIGATION MEASURES

						Job Title Agreement No. CE 14/2014 (HY) New Wang Tong River Bridge, Mui Wo Environmental Impact Assessment and Drainage Impact Studies – Investigation	Figure No. 8.12.1	The joint venture of Maurice Lee & Associates Ltd. and Cinotech Consultants Ltd.  						
					Drawing Title PHOTOMONTAGE VIEWPOINT P1: VIEW EAST FROM CHUNG HAU (1 OF 2)	Scale N.T.S.								
Rev. B	2015-12-30	Tree T4 retained; Tree 27 felled	LW	TO	TO									
Rev. A	2015-06-09	General update	LW	TO	TO									
Amendment No.	Date	Description	Drawn by	Checked by	Approved by	Drawn by	MC	Checked by	Approved by	TO	Date	2015-04	Job No.	MLAL1