






EXISTING CONDITIONS



DAY 1 WITHOUT MITIGATION MEASURES

						<b>Job Title</b> Agreement No. CE 14/2014 (HY) New Wang Tong River Bridge, Mui Wo Environmental Impact Assessment and Drainage Impact Studies – Investigation			<b>Figure No.</b> 8.13.1		The joint venture of Maurice Lee & Associates Ltd. and Cinotech Consultants Ltd.			
						<b>Drawing Title</b> PHOTOMONTAGE VIEWPOINT P2: VIEW WEST FROM SILVER MINE BAY BEACH (1 OF 2)			<b>Scale</b> N.T.S.		 Maurice Lee & Associates Ltd.			
Rev. B	2015-12-30	Tree T4 retained	LW	TO	TO						 cinotech consultants limited			
Rev. A	2015-06-09	General update	LW	TO	TO						 MUI WO LIMITED			
<b>Amendment No.</b>	<b>Date</b>	<b>Description</b>	<b>Drawn by</b>	<b>Checked by</b>	<b>Approved by</b>	<b>Drawn by</b>	MC	<b>Checked by</b>	<b>Approved by</b>	TO	<b>Date</b>	2015-04	<b>Job No.</b>	MLAL1