



EXISTING CONDITIONS




DAY 1 WITHOUT MITIGATION MEASURES



DAY 1 WITH MITIGATION MEASURES



YEAR 10 WITH MITIGATION MEASURES

						Job Title Agreement No. CE 41/2013 (EP) Port Shelter Sewerage, Stage 3 - Sewerage Works at Po Toi O Environmental Impact Assessment Studies - Investigation					FIGURE No.  10.16		 <b>Urbis Limited</b> Planning, Urban Design, Landscape, Golf & Environmental Consultants Urbis Limited, 11/F Siu On Centre, 188 Lockhart Road, Wan Chai, Hong Kong. Tel : 2802 3333 Fax : 2802 8662			
C	2016-06-06	YEAR 10 GREENING UPDATED	MC	TO	TO	Drawing Title  PHOTOMONTAGE VIEWPOINT 3 FROM TIN HA SHAN LOOKING EAST					Scale  NTS					
B	2016-03-29	ANNOTATIONS ADDED	PN	TO	TO											
A	2015-06-16	GENERAL REVISION	LW	TO	TO											
Amendment No.	Date	Description	Drawn by	Checked by	Approved by	Drawn by	PL	Checked by	KB	Approved by	TO	Date	2014-12-01	Job. No.	CTCL1	