





EXISTING CONDITIONS



DURING CONSTRUCTION WITHOUT MITIGATION MEASURES



DURING CONSTRUCTION WITH MITIGATION MEASURES



DAY 1 AND YEAR 10 WITH MITIGATION MEASURES

						Job Title					FIGURE No.		 Planning, Urban Design, Landscape, Golf & Environmental Consultants Urbis Limited, 11/F Siu On Centre, 188 Lockhart Road, Wan Chai, Hong Kong. Tel : 2802 3333 Fax : 2802 8662		
						Agreement No. CE 41/2013 (EP) Port Shelter Sewerage, Stage 3 - Sewerage Works at Po Toi O Environmental Impact Assessment Studies - Investigation					10.18				
						Drawing Title					Scale				
						PHOTOMONTAGE VIEWPOINT 5 FROM CLEAR WATER BAY SECOND BEACH LOOKING SOUTH EAST					1:15000				
A	2016-03-29	ANNOTATIONS ADDED	PN	TO	TO										
Amendment No.	Date	Description	Drawn by	Checked by	Approved by	Drawn by	PL	Checked by	KB	Approved by	TO	Date		2015-03-27	Job. No.