







Agreement No. CE 3/2015 (DS) Yuen Long Effluent Polishing Plant – Investigation, Design and Construction Water Level, Depth Averaged Current Velocity and Direction at DM2 in Dry Season Model results – Red: Base Case; Dashed Blue: Repeat Model Run	Dry Season	Nov 2018
	Appendix 5.8 – 01	
AECOM	/GPP/	Spchk.ssn




Agreement No. CE 3/2015 (DS) Yuen Long Effluent Polishing Plant – Investigation, Design and Construction Surface, Mid-Depth and Bottom Salinity at DM2 in Dry Season Model results – Red: Base Case; Dashed Blue: Repeat Model Run	Dry Season	Nov 2018
	Appendix 5.8 – 02	
AECOM	/GPP/	Spchk.ssn






Agreement No. CE 3/2015 (DS) Yuen Long Effluent Polishing Plant – Investigation, Design and Construction Water Level, Depth Averaged Current Velocity and Direction at DM2 in Wet Season Model results – Red: Base Case; Dashed Blue: Repeat Model Run	Wet Season	Nov 2018
	Appendix 5.8 – 03	
AECOM	/GPP/	Spchk.ssn









Agreement No. CE 3/2015 (DS) Yuen Long Effluent Polishing Plant – Investigation, Design and Construction Surface, Mid-Depth and Bottom Salinity at DM2 in Wet Season Model results – Red: Base Case; Dashed Blue: Repeat Model Run	Wet Season	Nov 2018
	Appendix 5.8 – 04	
AECOM	/GPP/	Spchk.ssn



Agreement No. CE 3/2015 (DS) Yuen Long Effluent Polishing Plant – Investigation, Design and Construction Surface, Mid-Depth and Bottom Temperature at DM2 in Wet Season Model results – Red: Base Case; Dashed Blue: Repeat Model Run	Wet Season	Nov 2018
	Appendix 5.8 – 05	
AECOM	/GPP/	Spchk.ssn






Agreement No. CE 3/2015 (DS) Yuen Long Effluent Polishing Plant – Investigation, Design and Construction Depth Averaged DO, BOD <sub>5</sub> and SS at DM2 in Dry Season Model results – Red: Base Case; Dashed Blue: Repeat Model Run	Dry Season	Nov 2018
	Appendix 5.8 – 06	
AECOM	/GPP/	Spchk.ssn



Agreement No. CE 3/2015 (DS) Yuen Long Effluent Polishing Plant – Investigation, Design and Construction Depth Averaged E. coli, TN and TP at DM2 in Dry Season Model results – Red: Base Case; Dashed Blue: Repeat Model Run	Dry Season	Nov 2018
	Appendix 5.8 – 07	
AECOM	/GPP/	Spchk.ssn

Agreement No. CE 3/2015 (DS) Yuen Long Effluent Polishing Plant – Investigation, Design and Construction Depth Averaged DO, BOD <sub>5</sub> and SS at DM2 in Wet Season Model results – Red: Base Case; Dashed Blue: Repeat Model Run	Wet Season	Nov 2018
	Appendix 5.8 – 08	
AECOM	/GPP/	Spchk.ssn



Agreement No. CE 3/2015 (DS) Yuen Long Effluent Polishing Plant – Investigation, Design and Construction Depth Averaged E. coli, TN and TP at DM2 in Wet Season Model results – Red: Base Case; Dashed Blue: Repeat Model Run	Wet Season	Nov 2018
	Appendix 5.8 – 09	
AECOM	/GPP/	Spchk.ssn