



EXISTING CONDITIONS



DAY 1 OPERATION WITH LANDSCAPE AND VISUAL MITIGATION MEASURES



DAY 1 OPERATION WITHOUT LANDSCAPE AND VISUAL MITIGATION MEASURES



YEAR 10 OPERATION WITH LANDSCAPE AND VISUALMITIGATION MEASURES



PROJECT MANAGEMENT DIVISION



CE 06/2010 (DS) IMPROVEMENT OF YUEN LONG TOWN NULLAH (TOWN CENTRE SECTION) -**INVESTIGATION**

PHOTOMONTAGE	FOR VANTAGE	POINT T2
		•

			'
DRAWING NO.			REVISION
FIG	FIGURE 9.8b		
AS SH	IOWN	JUN 2019	
DESIGNED		CHECKED	
WLL		DA	