

EXISTING CONDITIONS




DAY 1 OPERATION WITH LANDSCAPE AND VISUAL MITIGATION MEASURES



DAY 1 OPERATION WITHOUT LANDSCAPE AND VISUAL MITIGATION MEASURES



YEAR 10 OPERATION WITH LANDSCAPE AND VISUAL MITIGATION MEASURES



DESIGNING STRUCTURE BLENDING WITH SURROUNDING ENVIRONMENT

Drainage Services Department

PROJECT MANAGEMENT DIVISION



CE 06/2010 (DS)
IMPROVEMENT OF YUEN LONG TOWN NULLAH (TOWN CENTRE SECTION) -INVESTIGATION

PHOTOMONTAGE FOR VANTAGE POINT T3

				1
DRAWING NO.			REVISION	
FIGURE 9.8c			1	
AS SHOWN		JUN 2019		
DESIGNED		CHECKED		
WLL		DA		