



Monitoring Location Category

- Control
- ▲ Impact
- Species of Conservation Concern

- Work Limit Boundary
- 500m Study Area

Habitat

- Agricultural Land
- Pond
- Watercourse
- Grassland
- Grassland/Shrubland
- Secondary Woodland
- Plantation
- Waste Ground
- Urban/Residential Area

ATKINS

Project Title:
**Agreement No. CE 22/2013 (DS)
 Drainage Improvement Works in Yuen Long, Stage 1
 Investigation, Design and Construction**

Figure Title:
**Water Quality Monitoring Location
 At Sung Shan New Village**

Drawn by:	ST	Scale:	1:4,986 on A3
Checked By:	EL	Date:	Sep 2019
Approved by:	YX		
Figure Number:	Figure 6.5	Revision:	2