



- Monitoring Locations**
- Control
 - ▲ Impact
 - Species of Conservation Concern
 - 500m Study Area
 - Work Limit Boundary
 - Agricultural Land
 - Pond
 - Marsh
 - Mitigation Wetland
 - Watercourse
 - Seasonally Wet Grassland
 - Grassland
 - Grassland/Shrubland
 - Secondary Woodland
 - Orchard
 - Plantation
 - Waste Ground
 - Urban/Residential Area

ATKINS

Project Title:
Agreement No. CE 22/2013 (DS)
Drainage Improvement Works in Yuen Long, Stage 1
Investigation, Design and Construction

Figure Title:
Water Quality Monitoring Location
At Tai Wo

Drawn by:	ST	Scale:	1:4,995 on A3
Checked By:	EL	Date:	Sep 2019
Approved by:	JC		
Figure Number:	Figure 6.6		Revision: 2