

AECOM 8/F Grand Central Plaza, Tower 2 138 Shatin Rural Committee Road Shatin, Hong Kong 香港新界沙田鄉事會路 138 號 新城市中央廣場第 2 座 8 樓

www.aecom.com

+852 3922 9000 tel +852 3922 9797 fax

Our Ref: BCC:FMSC:mjj:60579757/5.2-2019007291T

26 June 2019

By Fax & Post (Fax: 2685 1133)

Environmental Protection Department Regional Office (North) 10/F, Sha Tin Government Offices, No.1 Sheung Wo Che Road, Sha Tin, New Territories

Dear Sir/Madam,

Agreement No. CE 8/2018 (HY)
Revised Trunk Road T4 and Associated Improvement Works in Sha Tin – Investigation

Request for Information of Chemical Waste Producer and Chemical Spillage Accident for "Revised Trunk Road T4 in Sha Tin" (EIA Study Brief No. ESB-315/2019)

AECOM Asia Co. Ltd. has been commissioned by Civil Engineering and Development Department as the Consultant to undertake land contamination assessment for the captioned project. The Project Boundary is indicated in the figures enclosed.

As part of the land contamination assessment and following the *Practice Guide for Investigation and Remediation of Contaminated Land* issued by EPD, we have to collect historical information regarding the past and present activities of the Project Boundary. To facilitate our assessment, we would like to request for the following information regarding the captioned Project Boundary:

- 1. Current and past (as early as the records are available) registered Chemical Waste Producer(s) within the Project Boundary (preferably with the registration date, status (moved out or active), nature and quantity of the chemical waste); and
- 2. Reported accidents of spillage / leakage of chemicals within the Project Boundary.

Please feel free to contact our Ms. Chloe Ng at 3922 9305 or Ms. Vanni Liu at 3922 9507 should you have any gueries.


Thank you very much for your kind assistance.


Yours faithfully, For and on behalf of AECOM Asia Co. Ltd.


Kelvin Cheng Executive Director


Transportation, Hong Kong


Encl.











本署檔案 OUR REF: 來函檔案 () in EP540/P5/1

YOUR REF: 電 話

TEL. NO.: 國文傳真 FAX NO.: 2158 5744 2650 6033

闰 址

HOMEPAGE: http://www.epd.gov.hk/

Environmental Protection Department Environmental Compliance Division Regional Office (North)

10/F., Shatin Government Offices, 1 Sheung Wo Che Road, Sha Tin, New Territories, Hong Kong.



環境保護署 環保法規管理科 區域辦事處(北) 香港新界沙田 上禾爺路一號 沙田政府合署10 樓

AECOM 8/F, Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, Hong Kong (Attn: Mr. Kelvin Cheng, Executive Director)

BY MAIL

28 June 2019

Dear Mr. CHENG,

Revised Trunk Road T4 in Shatin Request for Information of Chemical Spillage Accident

I refer to your letter dated 26 June 2019 on the captioned.

Regarding your enquiries in the above letter, this Regional Office has no record of reported accidents of spillage / leakage of chemicals at the concerned site. You may need to check with other parties / departments for such information as appropriate.

A registry of chemical waste producers is available in the Territory Control Office of this department. Please contact Mr. Eric FUNG, Senior Environmental Protection Inspector at 2835 1027 for making an appointment to view the records.

Should you have any enquiry, you may contact my colleague Mr. LO at 2158 5845

Yours faithfully,

(NG Wai-yin, Jackie)
Regional Office / North

for Director of Environmental Protection



AECOM 8/F Grand Central Plaza, Tower 2 138 Shatin Rural Committee Road Shatin, Hong Kong 香港新界沙田鄉事會路 138 號 新城市中央廣場第 2 座 8 樓

www.aecom.com

+852 3922 9000 tel +852 3922 9797 fax

Our Ref: BCC:FMSC:mjj:60579757/5.2-2019007292T

26 June 2019

By Fax & Post (Fax: 2367 3631)

Fire Services Department Licensing and Certification Command 5/F, South Wing, Fire Services HQ Building 1 Hong Chong Road Tsim Sha Tsui East, Kowloon

Dear Sir/Madam,

Agreement No. CE 8/2018 (HY)
Revised Trunk Road T4 and Associated Improvement Works in Sha Tin – Investigation

Request for Information about Dangerous Goods Store and Incidents Records for "Revised Trunk Road T4 in Sha Tin" (EIA Study Brief No. ESB-315/2019)

AECOM Asia Co. Ltd. has been commissioned by Civil Engineering and Development Department as the Consultant to undertake land contamination assessment for the captioned project. The Project Boundary is indicated in the figures enclosed.

As part of the land contamination assessment and following the *Practice Guide for Investigation and Remediation of Contaminated Land* issued by EPD, we have to collect historical information regarding the past and present activities of the site. To facilitate our assessment, we would like to request for the following information regarding the captioned site:

- 1. Records of current and past (as early as the records are available) registration of Dangerous Goods storage (with type of dangerous goods, storage method, quantity, licence no., date of issue and storage location) within the Project Boundary;
- 2. Any records of reported accidents of spillage/leakage of dangerous goods stored within the Project Boundary; and
- 3. Any records of fire incidents within the Project Boundary.

Please feel free to contact our Ms. Chloe Ng at 3922 9305 or Ms. Vanni Liu at 3922 9507 should you have any queries.


Thank you very much for your kind assistance.


Yours faithfully, For and on behalf of AECOM Asia Co. Ltd.


Kelvin Cheng Executive Director


Transportation, Hong Kong


Encl.











消防處 香港九龍尖沙咀東部康莊道 L號 消防總部大廈



FIRE SERVICES DEPARTMENT FIRE SERVICES HEADQUARTERS BUILDING, No.1 Hong Chong Road, Tsim Sha Tsui East, Kowloon, Hong Kong.

本處檔號 OUR REF.

(85) in FSD GR 6-5/4 R Pt. 23

來函檔號 YOUR REF. :

BCC:FMSC:mjj:60579757/5.2-2019007292T

電子郵件 E-mail

hkfsdenq@hkfsd.gov.hk

圖文傳真 FAX NO.

2739 5879

電 話 TEL NO.

2733 7741

22 July 2018

AECOM Asia Co. Ltd 8/F, Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, Hong Kong.

(Attn: Mr. Kelvin CHENG, Executive Director, Transportation)

Dear Mr. CHENG,

Agreement No. CE 8/2018 (HY) Revised Trunk Road T4 in Sha Tin (EIA Study Brief No. ESB-315/2019) Request for Information of Dangerous Goods & Incident Records

I refer to your letter of 26.6.2019 and subsequent letter dated 5.7.2019 regarding the captioned request and reply below in response to your questions:-

- 1. According to our record, from the year of 1990 to present moment, dangerous goods licenses have been issued by this department to the subject address, with details as shown in **Appendix A**.
- 2. A total of one incident record was found at the subject location. Please refer to **Appendix B** for details.

If you have further questions, please feel free to contact the undersigned.

Yours sincerely,

(KONG Wai-chung)
for Director of Fire Services

Agreement No. CE 8/2018 (HY) Revised Trunk Road T4 in Sha Tin (EIA Study Brief No. ESB-315/2019) Request for Information of Dangerous Goods & Incident Records

<u>Item</u>	Type of DG	Quantity	Storage Method
1.	Petrol	45000 Litres	Underground Tank in
2.	Diesel Oils	45000 Litres	Petrol Filling Station

Agreement No. CE 8/2018 (HY) Revised Trunk Road T4 in Sha Tin (EIA Study Brief No. ESB-315/2019) Request for Information of Dangerous Goods & Incident Records

Date	Type of Incident	Address
10/3/2017	No.1 Alarm Fire	Transport City Building