




APPENDIX 10C SIDE SCAN SONAR IMAGES OF SONAR CONTACTS


Appendix 10C: Side Scan Sonar Images of Sonar contacts

Site C1














C1-SC006: Debris























C1-SC017: Debris








C1-SC019: Debris


Site C2















C2-SC006: Linear debris












C2-SC010: Debris





C2-SC011: Tire







C2-SC013: Debris









C2-SC016: Possible linear contact




C2-SC017: Possible linear contact





C2-SC018: Possible linear contact




C2-SC019: Debris











C2-SC023: Unknown object














C2-SC031 Debris

