



THE GOVERNMENT OF THE HONG KONG
SPECIAL ADMINISTRATIVE REGION
DRAINAGE SERVICES DEPARTMENT

**Agreement No. CE54/2019 (DS)
Revitalisation of Tai Wai Nullah and Fo Tan Nullah – Investigation
Revitalisation of Tai Wai Nullah**

**Environmental Impact Assessment Report
Volume II – Figures & Appendices**

AECOM Asia Co. Ltd.

February 2023

List of Figures

Figure 2.1	Project Location Plan
Figure 2.2	General Layout Plan of Revitalisation of Tai Wai Nullah
Figure 2.3	Interactions with Other Projects
Figure 3.1	Locations of Air Sensitive Receivers
Figure 4.1	Locations of Noise Sensitive Receivers and Representative Noise Assessment Points
Figure 5.1	Locations of Water Sensitive Receivers and EPD Monitoring Stations
Figure 7.1	Photographic Records of Site Walkover (Tai Wai Nullah) (Sheet 1 of 3)
Figure 7.2	Photographic Records of Site Walkover (Tai Wai Nullah) (Sheet 2 of 3)
Figure 7.3	Photographic Records of Site Walkover (Tai Wai Nullah) (Sheet 3 of 3)
Figure 8.1	Layout Plan for Proposed Dry Weather Flow Interceptor (DWFI) System for Tai Wai Nullah (Sheet 1 of 3)
Figure 8.2	Layout Plan for Proposed Dry Weather Flow Interceptor (DWFI) System for Tai Wai Nullah (Sheet 2 of 3)
Figure 8.3	Layout Plan for Proposed Dry Weather Flow Interceptor (DWFI) System for Tai Wai Nullah (Sheet 3 of 3)
Figure 9.1	Locations of Terrestrial Ecological Surveys
Figure 9.2	Locations of Marine Ecological Surveys
Figure 9.3	Habitat Map and Locations of Species of Conservation Importance (Key Plan)
Figure 9.3A	Habitat Map and Locations of Species of Conservation Importance (Sheet 1 of 3)
Figure 9.3B	Habitat Map and Locations of Species of Conservation Importance (Sheet 2 of 3)
Figure 9.3C	Habitat Map and Locations of Species of Conservation Importance (Sheet 3 of 3)
Figure 9.4	Flight Path of Ardeids at Downstream of Tai Wai Nullah
Figure 10.1	Key Fisheries Resources within Assessment Area
Figure 11.1	Locations of Built Heritage within the 300m Assessment Area
Figure 11.2	Location of the Declared Monument within 300m from Discharge Area of Tai Wai Nullah
Figure 11.3	Published Geological Map - Tai Wai Nullah
Figure 11.4	Topographic Maps of 1956 to 1958 showing the Project Site
Figure 12.1	Landscape Impact Assessment Area
Figure 12.2	Review of Planning & Development Control Framework
Figure 12.3	Location of Landscape Resource Plan
Figure 12.4	Location of Landscape Character Area
Figure 12.5	Photographic Records for LRs & LCAs
Figure 12.6	Visual Envelope & Visually Sensitive Receivers
Figure 12.7	Photomontage of VP1
Figure 12.8	Photomontage of VP2
Figure 12.9	Photomontage of VP3
Figure 12.10	Photomontage of VP4
Figure 12.11	Photomontage of VP5
Figure 12.12	Landscape & Visual Mitigation Plan (Sheet 1 of 2)
Figure 12.13	Landscape & Visual Mitigation Plan (Sheet 2 of 2)
Figure 12.14	Photographic Records of identified OVTs within 100m Assessment Boundary
Figure 12.15	Photographic Records of Identified TPIs within Project Boundary

List of Appendices

Appendix 2.1	Master Layout Plan of Revitalisation of Tai Wai Nullah
Appendix 2.2	Tentative Construction Programme
Appendix 2.3	Confirmation of No Change in EIA Study Brief
Appendix 4.1	Determination of Fixed Plant Noise Criteria
Appendix 4.2	Locations of Works Area and Noise Assessment Points
Appendix 4.3	Construction Plant Inventory (Unmitigated Scenario)
Appendix 4.4	Unmitigated Construction Noise Calculation
Appendix 4.5	Operation Phase Fixed Plant Noise Calculation (Unmitigated Scenario)
Appendix 4.6	Construction Plant Inventory (Mitigated Scenario)
Appendix 4.7	Mitigated Construction Noise Calculation
Appendix 4.8	Further Mitigated Construction Noise Calculation for NAP11 and NAP16
Appendix 4.9	Cumulative Construction Noise Calculation
Appendix 7.1	Reviewed Aerial Photographs
Appendix 7.2	Acquisition of Information from Government Departments
Appendix 7.3	Site Walkover Checklist
Appendix 8.1	Hydraulic Performance of Existing Sewers
Appendix 9.1	Rapid Ecological Assessment
Appendix 9.2	Representative Photographs of Habitat Types Recorded within the Assessment Area
Appendix 9.3	Flora Species Recorded within the Assessment Area
Appendix 9.4	Representative Photographs of Species of Conservation Importance Recorded
Appendix 9.5	Fauna Species Recorded within the Assessment Area
Appendix 9.6	Benthos Survey Results (Abundance) for Both Dry and Wet Season
Appendix 9.7	Raw Data Recorded during Intertidal Surveys within the Assessment Area during Both Dry and Wet Season
Appendix 11.1	Aerial Photos of the Project Site
Appendix 11.2	Built Heritage Recording Sheets
Appendix 15.1	Key Assumptions and Limitations
Appendix 15.2	Summary of Environmental Impacts