




VP02 – BUS STOP (SKH ST PETER'S CHURCH) ON TSING WUN ROAD (SOUTHBOUND) - EXISTING SITE CONDITION




VP02 – BUS STOP (SKH ST PETER'S CHURCH) ON TSING WUN ROAD (SOUTHBOUND) - WITHOUT MITIGATION MEASURES



VP02 – BUS STOP (SKH ST PETER'S CHURCH) ON TSING WUN ROAD (SOUTHBOUND) - DAY 1 WITH MITIGATION MEASURES



VP02 – BUS STOP (SKH ST PETER'S CHURCH) ON TSING WUN ROAD (SOUTHBOUND) - YEAR 10 WITH MITIGATION MEASURES



KEY PLAN

MITIGATION MEASURES (CONSTRUCTION PHASE)

CM1	Preservation of Existing Vegetation
CM2	Transplanting of Affected Trees
CM3	Control of Night-time Lighting Glare
CM4	Good Site Practice
CM5	Erection of Decorative Screen Hoarding

MITIGATION MEASURES (OPERATION PHASE)

OM1	Compensatory Tree Planting
OM2	Roadside Planting
OM3	Aesthetically treatment Noise Barrier
OM4	Aesthetically pleasing design

B	DRAFT ISSUE 4	BN	MAR 23
A	DRAFT ISSUE 3	BN	NOV 22
Rev	Description	By	Date



Project title
TRAFFIC IMPROVEMENT SCHEME IN TUEN MUN
– WIDENING AND ADDITION OF SLIP ROADS
AT LUNG FU ROAD/ TUEN MUN ROAD/
WONG CHU ROAD/ HOI WING ROAD

Drawing title
PHOTOMONTAGE VIEWPOINT 02

Drawing no.	FIGURE 9.8.2	Rev.	B
Drawn	Date	Checked	Approved
Scale	N.T.S.	Status	FOR INFORMATION

