

VP04 – PEDESTRIAN FOOTPATH ALONG TSING WUN ROAD (NORTHBOUND) - EXISTING SITE CONDITION




VP04 – PEDESTRIAN FOOTPATH ALONG TSING WUN ROAD (NORTHBOUND) - DAY 1 WITH MITIGATION MEASURES



VP04 – PEDESTRIAN FOOTPATH ALONG TSING WUN ROAD (NORTHBOUND) - WITHOUT MITIGATION MEASURES



VP04 – PEDESTRIAN FOOTPATH ALONG TSING WUN ROAD (NORTHBOUND) - YEAR 10 WITH MITIGATION MEASURES



MITIGATION MEASURES (CONSTRUCTION PHASE)					
CM1	Preservation of Existing Vegetation				
CM2	Transplanting of Affected Trees				
СМЗ	Control of Night-time Lighting Glare				
CM4	Good Site Practice				
CM5	Erection of Decorative Screen Hoarding				
MITIGATION MEASURES (OPERATION PHASE)					
OM1	Compensatory Tree Planting				
OM2	Roadside Planting				
ОМ3	Aesthetically treatment Noise Barrier				
OM4	Aesthetically pleasing design				

В	DRAFT ISSUE 4	BN	MAR 23			
Α	DRAFT ISSUE 3	BN	NOV 22			
Rev	Description	Ву	Date			
Consultant						

TRAFFIC IMPROVEMENT SCHEME IN TUEN MUN

- WIDENING AND ADDITION OF SLIP ROADS
AT LUNG FU ROAD/ TUEN MUN ROAD/
WONG CHU ROAD/ HOI WING ROAD

PHOTOMONTAGE VIEWPOINT 04

Drawing no.	FIGURE 9.8.4			Rev. B	
Drawn	Date MAR 2023	Checked BN	A	Approved CL	
Scale N.T.	Status FOR INFORMATION				
	(A) 00DVD10	LIT DECEDVED			

